




# INSTRUMENTATION



Printable Workbook included in the DVD

PLT  
620,0044  
In 5/1  
2014  
+



# INSTRUMENTATION



3G eLEARNING

# TABLE OF CONTENTS

<b>1. Measurements and Instrumentation</b>	<b>33</b>
1.1 Static Characteristics of Instrument Systems	3
1.1.1 Output/Input Relationship	3
1.1.2 Drift	7
1.1.3 Hysteresis and Backlash	7
1.1.4 Saturation	8
1.1.5 Bias	9
1.1.6 Error of Nonlinearity	10
1.2 Dynamic Characteristics of Instrument Systems	12
1.2.1 Dealing with Dynamic States	12
1.2.2 Forcing Functions	14
1.2.3 Characteristic Equation Development	14
1.2.4 Response of the Different Linear Systems Types	16
1.3 Operational Modes of Instrumentation	22
1.3.1 Null Instrument	22
1.3.2 Analog and Digital Sensors	25
1.3.3 Analog and Digital Readout Instruments	27
1.3.4 Input Impedance	28
1.4 Standards of Measurements and Their Classification	29
1.4.1 Primary Standard	30
1.4.2 Secondary Standard	30
1.5 Standard Unit of Length	30
<b>2. Measurement of Force, Torque and Velocity</b>	
2.1 Measurement of Force	33
2.1.1 Physical Quantities	34
2.1.2 Method	36
2.2 Electric Balance	39
2.2.1 How Electronic Balances Work	40
2.3 Different Types of Load Cells	41
2.3.1 Strain Gauge Load Cells	41
2.3.2 Elastic Load cell	45
2.3.3 Magneto-Elastic Load Cell	46
2.4 Torque	47
2.4.1 Rotating Vs. Nonrotating Transducers	48
2.4.2 Torque Measurement	49
2.4.3 Torque Applications	51
2.5 Strain-Gauge Torque	52
2.5.1 Balancing Machines	54
2.6 Speed Measurement	57
2.6.1 Measuring methods	57
2.6.2 Types of Tachometer	58
2.6.3 Stroboscopic Method	60
2.7 Transducers	60
2.7.1 Display Units	62
2.7.2 Accessories	64
2.7.3 Measured Drawings of the Eddy	68
2.8 Revolution Counters	70
2.8.1 Electronic Tachometer with Integrated Hour Meter	72
<b>3. Measurement of Acceleration, Vibration, Density and Viscosity</b>	
3.1 Accelerometers	75
3.1.1 INDT Accelerometer	78

3.2	<b>Types of accelerometers</b> .....	79	4.3	<b>Barometers</b> .....	127
3.2.1	Piezoelectric Accelerometer.....	79	4.3.1	Liquid in Glass Barometer.....	127
3.2.2	Piezoresistive Accelerometer.....	96	4.3.2	Aneroid Barometer.....	128
3.2.3	Strain gage accelerometers.....	97	4.4	<b>Bourdon Vacuum Gauge</b> .....	129
3.2.4	Seismic instruments as accelerometer.....	97	4.4.1	Capsule Vacuum Gauge.....	130
3.2.5	Vibration Instruments.....	98	4.4.2	Diaphragm Vacuum Gauge.....	131
3.3	<b>Laser Doppler Vibrometers</b> .....	99	4.4.3	Capacitance Vacuum Gauge.....	131
3.3.1	Optical Sensors for Vibration Measurements.....	101	4.5	<b>Thermal Conductivity Gauge (Pirani)</b> .....	132
3.4	<b>Measurement of Density</b> .....	102	4.5.1	Cold Cathode Ionization Vacuum Gauge (Penning).....	133
3.4.1	Density.....	102	4.5.2	Hot Cathode Ionization Vacuum Gauge.....	134
3.4.2	Relative Density (Specific Gravity).....	103	4.6	<b>Hot Vs. Cold Ionization Gauges</b> .....	134
3.4.3	Specific Weight.....	105	4.6.1	Hot-Cathode Gauges (HCG).....	135
3.4.4	Specific Gravity (Relative Density).....	106	4.6.2	Cold-Cathode Gauges (CCG).....	137
3.5	<b>Baume Scale</b> .....	107	4.7	<b>Calibration of Pressure Gages</b> .....	140
3.6	<b>API Scale</b> .....	108	4.7.1	Apparatus.....	141
3.7	<b>Densitometer</b> .....	110	4.7.2	Procedure.....	141
3.7.1	Pressure Head Type Densitometer.....	110	4.7.3	Data Reduction.....	142
3.7.2	Float Type Densitometer.....	111	4.7.4	Report.....	142
3.7.3	Ultrasonic Densitometer.....	111	4.8	<b>Methods of Calibration</b> .....	144
3.7.4	Bridge Type Gas Densitometer.....	111	4.8.1	Fundamental Characterization of Deadweight Testers.....	144
3.8	<b>Saybolt Viscometer</b> .....	111	4.8.2	Calibrated Characterization of Deadweight Testers.....	145
4.	<b>Pressure Measurement</b>		4.9	<b>Test Equipment for a Pressure Standards Laboratory</b> .....	145
4.1	<b>Liquid Manometers</b> .....	114	4.9.1	Hydraulic Piston-Cylinder Deadweight Testers.....	146
4.1.1	Differential Pressure is a Comparison of One Pressure to Another.....	115	4.9.2	Pneumatic Floating Ball Deadweight Testers.....	148
4.2	<b>Elastic Pressure Sensors</b> .....	119	4.10	<b>Frequency of Calibration</b> .....	148
4.2.1	Elastic Pressure Sensors Initially Convert Pressure into a Displacement.....	119	4.10.1	Frequency of Recertification and Recalibration of Piston and Cylinder Type Deadweight Testers.....	148
4.2.2	Bourdon Tube Pressure Gauge.....	120	4.10.2	Frequency of Recertification of Floating Ball Type Pneumatic Type deadweight Testers.....	149
4.2.3	Bellows.....	121	5.	<b>Temperature Measurement</b>	
4.2.4	Capacitive Pressure Sensors.....	123	5.1	<b>Temperature</b> .....	152
4.2.5	Piezoelectric Pressure Sensor.....	125			
4.2.6	Piezoresistive and Strain Gauge Pressure Sensors.....	126			



5.1.1	The International Temperature Scale ITS-90.....	153	5.8.1	The Fixed Temperature Points.....	178
5.1.2	Defined Fixed Points.....	154	5.8.2	The Temperature Scale According To ITS-90.....	178
<b>5.2</b>	<b>Thermometer.....</b>	<b>156</b>	5.8.3	The Measurement Uncertainty.....	179
5.2.1	Primary and Secondary Thermometers.....	156	5.8.4	The Measurement Process.....	180
<b>5.3</b>	<b>Calibration of Thermometer.....</b>	<b>157</b>	<b>5.9</b>	<b>RTD Instrumentation.....</b>	<b>181</b>
5.3.1	Platinum Thermometers.....	158	5.9.1	Two, Three and Four Wire RTDs.....	182
5.3.2	Thermistor Thermometers.....	158	5.9.2	Traditional Instruments Measure Resistance.....	183
5.3.3	Calibration.....	159	5.9.3	New Instruments Measure Resistance.....	183
5.3.4	Calibration Services.....	160	5.9.4	New Instruments Simulate Resistance.....	184
5.3.5	Calibration Information.....	162	5.9.5	Temperature Transmitters.....	184
5.3.6	Generation of the Calibration Equations.....	162	<b>6.</b>	<b>Thermocouples and Pyrometers</b>	
5.3.7	Electrical Measurements.....	163	<b>6.1</b>	<b>Thermocouples.....</b>	<b>188</b>
<b>5.4</b>	<b>Filled System Thermometers.....</b>	<b>164</b>	6.1.1	Working Principle.....	190
5.4.1	Filled Systems.....	165	6.1.2	Laws of Thermocouple.....	191
5.4.2	Filled System Thermometer Vendors.....	165	<b>6.2</b>	<b>Fabrication of Thermocouples.....</b>	<b>192</b>
<b>5.5</b>	<b>Systems and Their Compensation..</b>	<b>166</b>	6.2.1	Type N.....	193
5.5.1	Tips for Setting up Compensation.....	167	6.2.2	Type K.....	193
<b>5.6</b>	<b>Bimetallic Thermometers.....</b>	<b>167</b>	6.2.3	Type E.....	193
5.6.1	Gas-filled Thermometers.....	167	6.2.4	Type J.....	193
5.6.2	Accuracy.....	168	<b>6.3</b>	<b>Signal Conditioning of Thermocouples Output.....</b>	<b>194</b>
5.6.3	Ambient Temperature Compensation.....	168	<b>6.4</b>	<b>Thermal Block Reference Junctions</b>	<b>196</b>
<b>5.7</b>	<b>Electrical Methods of Temperature Measurement.....</b>	<b>168</b>	6.4.1	Cold Junction Compensation.....	203
5.7.1	Contact Temperature Measurement.....	169	<b>6.5</b>	<b>Response of Thermocouple.....</b>	<b>210</b>
5.7.2	Electrical Temperature Measurement.....	170	<b>6.6</b>	<b>Special Techniques for Measuring High Temperature Using Thermocouples.....</b>	<b>212</b>
5.7.3	Non-Contact Temperature Measurement.....	171	<b>6.7</b>	<b>Temperature Measurement Techniques.....</b>	<b>220</b>
5.7.4	Total Radiation Pyrometer.....	172	<b>6.8</b>	<b>Pyrometers.....</b>	<b>222</b>
5.7.5	Spectral Pyrometer.....	172	<b>6.9</b>	<b>Radiation Fundamental.....</b>	<b>224</b>
5.7.6	Band Radiation Pyrometer.....	172	6.9.1	Types of Radiation Thermometers.....	226
5.7.7	Radiation Density Pyrometer.....	172	6.9.2	Radiation Methods of Temperature Measurement.....	234
5.7.8	Distribution Pyrometer.....	172	<b>6.10</b>	<b>Two Color Radiation</b>	
5.7.9	Ratio Pyrometer.....	173			
<b>5.8</b>	<b>The Concept of Temperature.....</b>	<b>173</b>			

