


AUDEL™

# MACHINE SHOP TOOLS & OPERATIONS

ALL NEW 5TH EDITION

Rex Miller & Mark Richard Miller

12787-m  
621.7  
M649  
2004



# Audel<sup>TM</sup>

## Machine Shop Tools and Operations

### All New 5th Edition

Rex Miller  
Mark Richard Miller



Wiley Publishing, Inc.

# **Contents**

---

Acknowledgments	vii
About the Authors	ix
Introduction	xi
<b>Chapter 1: Power Hacksaws, Power Band Saws, and Circular Saws</b>	<b>1</b>
<b>Chapter 2: Basic Machine Tool Operations</b>	<b>25</b>
<b>Chapter 3: Drilling Machines</b>	<b>39</b>
<b>Chapter 4: Drilling Machine Operations</b>	<b>51</b>
<b>Chapter 5: Vertical Boring Mills and Horizontal Boring Machines</b>	<b>83</b>
<b>Chapter 6: Lathes</b>	<b>107</b>
<b>Chapter 7: Lathe Operations</b>	<b>135</b>
<b>Chapter 8: Cutting Screw Threads on the Lathe</b>	<b>167</b>
<b>Chapter 9: Lathe Attachments</b>	<b>195</b>
<b>Chapter 10: Turret Lathes</b>	<b>209</b>
<b>Chapter 11: Milling Machines</b>	<b>233</b>
<b>Chapter 12: Milling Machine Operations</b>	<b>241</b>
<b>Chapter 13: Milling Machine Dividing Heads</b>	<b>267</b>
<b>Chapter 14: Indexing Operation</b>	<b>281</b>
<b>Chapter 15: Shapers</b>	<b>301</b>

**iv** **Contents**

<b>Chapter 16: Planers</b>	<b>325</b>
<b>Chapter 17: Slotters</b>	<b>341</b>
<b>Chapter 18: Abrasive Metal Finishing Machines</b>	<b>353</b>
<b>Chapter 19: Electroforming</b>	<b>365</b>
<b>Chapter 20: Ultrasonics in Metalworking</b>	<b>379</b>
<b>Chapter 21: Machine Shop Robotics and Electronics</b>	<b>389</b>
<b>Appendix</b>	<b>405</b>
<b>Index</b>	<b>427</b>

# Index

---

## A

abrasive blasting, 358, 363  
abrasive machining, 34, 35, 36  
abrasive metal finishing, 353–363  
  abrasive blasting, 358–359  
  barrel and vibratory tanks, 359,  
    363  
  belt sanders, 359–361  
  grinding, types of, 353  
  grinding wheels, 355–358  
  safety and, 362–363  
abrasives, ultrasonic machining,  
  379–380  
abrasive tumbling, 359, 363  
abrasive wheel, 356  
Acme screw threads, 167, 169,  
  183, 192  
air-hydraulic vise, 75  
allowance, 172–173  
alternate-set saw blade, 7  
aluminum, cutting, 9  
American National screw thread  
  forms, 168, 192  
American Standard Acme screw  
  threads, 169  
American Standard Association,  
  168  
American Standard buttress  
  screwthreads, 170  
American Standard cap screws,  
  416  
American Standard for Unified  
  miniature screw threads, 170  
American Standard for Unified  
  screw threads, 168–169  
American Standard hexagon  
  socket, slotted headless, and  
  square-head setscrews,  
  414–415  
American Standard machine  
  screws, 413–414

American Standard Stub Acme  
  screw threads, 169  
angle of thread, 173  
angle plate, 77–78, 151  
angular indexing, 297  
apron, lathe, 115, 118, 119  
arbors, mounting, 250–253  
arm, robot, 390–391  
automatic-cycle drilling, 64  
automatic-cycle tapping, 64  
automatic drilling machines,  
  63–64  
  automatic cycling, 64  
  dial-type limit-setting controls,  
    63–64, 65  
  uses of, 63  
automatic feed. *See* power  
  feed  
automatic feed stops, 198–200,  
  207  
  ball-type cross-feed stop,  
    199–200, 207  
  carriage stops, 198–199  
  cross-slide stop, 199–200  
  micrometer carriage stop, 198,  
    207  
  automatic power feed, shapers,  
    304  
  automatic reverse feed handle  
    control, 66, 68  
  automatic tool changer, 26  
axis of screw, 174

## B

back-geared drill press, 45, 46  
back-geared lathe, 110  
back gears, drill press, 40, 42  
backlash, 320  
ball center, 128  
ball-type cross-feed stop,  
  199–200, 207

band saws, power, 4-18, 22  
 average speeds and cutting rates, 14-16  
 basic construction of, 4-7  
 blades, 6-8, 22  
 capacity, 6  
 classification of, 4-5  
 common problems and their connections, 12-14  
 cutting fluids, recommended, 10-12, 22  
 feeds, 12, 23  
 friction cutting speeds for common metals, 17-18  
 and hacksaws compared, 6  
 operation of, 7-18  
 bar machines, 210, 231  
 barrel finishing, 359, 360, 361, 363  
 base  
 drill press, 44, 49  
 robot, 390  
 shaper, 302, 323  
 base of thread, 174  
 basic, 174  
 bed  
 lathe, 110, 111  
 planer, 325, 339  
 bed turret, 204, 206, 208  
 bed-type milling machines, 238-239  
 belt sanders, 359, 361, 363  
 bench grinder, 354  
 bench-type sensitive drill press, 39, 40, 44, 49  
 bent-tail dog, 130  
 Bickford radial drilling machine, 60, 61, 68, 72  
 Bickford upright drilling machine, 64, 65  
 blades  
 alternate-set, 7  
 circular saws, 19-22, 23  
 flexible, 2  
 hook-tooth, 6-7, 16  
 pitch selection, 21  
 power band saws, 6-8, 22

power hacksaws, 2-3, 22  
 raker-set, 7, 15  
 skip-tooth, 6  
 speeds and, 14, 21  
 spindle speeds, 22  
 teeth per inch, 20-21  
 tooth sets for, 7  
 block indexing, 298, 299  
 boring  
 defined, 155, 164  
 drill press, 30, 71, 81  
 horizontal boring machine, 94-104, 105-106  
 on lathes, 155, 164, 220  
 vertical boring mill, 85-87  
 braces, 310-311, 312  
 brass, cutting, 4, 261  
 broaches, 33  
 bronze, cutting, 4  
 buffing, 71  
 bull gear, 304, 329  
 burring, 71  
 buttress screw thread form, 167, 170

**C**

camlock spindle, 120, 121  
 capacitor discharge machining, 35  
 carbon steel, colors and approximate temperatures of, 406  
 carriage, lathes, 109, 113, 115, 151-153  
 carriage stops, 198-199  
 cast iron, cutting, 9, 22, 261, 299  
 center drilling, 139-140, 141, 142, 164  
 centerless grinding, 359  
 center punch, drill, 51  
 centers, lathe, 126-129, 318  
 alignment of, 138-139  
 chamfer, 191  
 change-gear ratio, calculating, 177  
 change gears, 177-182  
 compound gearing, 177, 178, 179-182

- for differential indexing, 295-296  
 quick-change gear lathes, 182-183  
 selecting, 276  
 setting up, 278  
 simple gearing, 177-179  
 chucks  
     attaching, 120-121  
     collets, 125, 126, 214, 220, 232  
 drill press, 49, 71-72, 73, 81  
 four-jaw (independent), 122-123  
 lathes, 119-125  
 three-jaw (universal), 121-122  
 turret lathes, 214, 221, 222  
 use of, pointers on, 123-124  
     vertical boring mill, 89  
 chucking machines, 210, 231  
 chuck-unchuck lever, 214, 232  
 circular saws, 18-22, 23  
     advantages of, 18, 23  
     blades, 19-22, 23  
     cutting speed, 21  
     nonferrous saw, 18-19, 20  
     vises and, 19  
 clamp dog, 130  
 clamps  
     in machining operations, general, 78-79  
     in milling machine operations, 243  
     in planing operations, 332, 339  
     and shapers, 306-308  
 Clausing machine vise, 75  
 clearance  
     crest, 175  
     zero front, 143, 164  
 clearance angle, cutters, 248-249  
 climb milling, 253-254  
 coarse-thread screw thread series (UNC), 171-172  
 cold extrusion, 35, 36  
 collet chuck, 214, 220, 232  
 collets, 125, 126, 220  
 columns, planer, 327  
 combustion machining, 35  
 compound angular indexing, 297-298, 299  
 compound differential indexing, 294-295  
 compound gears, 177, 178, 179-181  
 compound indexing, 289-294, 299  
     index circles, determining which to use, 292-294  
 negative compounding, 291-292  
 and plain indexing combined, 294  
 positive compounding, 290  
     uses of, 289, 293  
 compound rest, 113, 116-117  
     in cutting screw threads, 187  
     taper turning with, 161-162  
 compounding  
     negative, 291-292  
     positive, 290  
 computers, applications for machinists, 36-37, 397-402, 403  
 conventional milling, 253  
 coolants  
     for milling machine operations, 261, 265  
     for power band saws, 5-6, 9  
     for power hacksaws, 2  
 core diameter, 175  
 counterboring, 49, 66  
 countersinking, 49, 66, 69  
 crest, 175  
 crest clearance, 175  
 crossrail  
     planers, 327-328, 339  
     shapers, 302, 323  
 cross slide, 113, 115, 223  
 cross-slide carriage, 113, 213-214  
 cross-slide stop, 199-200  
 crotch center, 129, 154  
 cutters  
     clearance angle, 248-249  
     double-angle, 246  
     end mill, 246  
     fly, 246

cutters (*continued*)  
 formed, 246  
 half side, 246  
 helical, 246  
 holding devices for, 71–74  
 inserted-tooth, 246  
 interlocking side, 246  
 laser (light beam), 35  
 location of, 254–255  
 mounting, 250–253  
 nicked, 246  
 plain, 246  
 rotation, direction of, 253–254  
 selecting, 246–247  
 sharpening, 247–249  
 side, 246  
 single-angle, 246  
 slitting, 247  
 slotting, 247  
 speed. *See* cutting speeds  
 types, compared, 247  
 ultrasonic, 382  
 cutting fluids, recommended,  
 10–11, 22  
 cutting oil, screw threads, 188  
 cutting performance, ultrasonics  
 and, 382–385  
 cutting speeds  
 circular saws, 21  
 for common metals, 17–18  
 lathes, 135–137, 164  
 milling machines, 255–257  
 power hacksaws, 4  
 shapers, 321–323  
 slotters, 350–351  
 cutting tools  
 diamond-impregnated, 385  
 on lathes, 143–145  
 new developments in, 385  
 on planers, 331–332, 338–339  
 screw threads, 183–187, 192  
 scriber, 350, 352  
 shapers, 305, 323  
 slotters, 349–350, 352  
 cutoff operations, turret lathe,  
 219–220  
 cutoff slide, vertical, 219

cutoff tool, 149, 218  
 cutoff toolholder, 229

**D**

Dardelet thread, 170  
 dead center, 126–127  
 decimal equivalents, squares,  
 cubes, square and cube roots,  
 and circumferences and areas  
 of circles  
 from 1/64 to 5/8 inch, 418–419  
 from 41/64 to 1 inch, 420  
 depth of engagement, 175  
 depth of thread, 175  
 dial-type limit-setting automatic  
 drilling controls, 63–64, 65  
 diamond tool, 356  
 differential indexing, 294–296,  
 299  
*change gears*, selecting,  
 295–296  
 compound, 295  
 gear arrangement, 294  
 simple, 295  
 direct indexing, 282–284,  
 298–299  
 dividing heads  
*calculating indexing on*,  
 286–289  
 classification of, 268–275, 278  
 defined, 267, 278, 281  
 and driving mechanism,  
 275–278  
 helical, 272–275, 278  
 indexing, 281–298  
 plain, 268–269, 270, 274, 278  
 plain indexing with, 284–286  
 power rapid traverse and, 276,  
 278  
 setting up, 272, 275–278  
 sizes, 278  
 types of, 268, 278  
 universal, 262, 263, 269–272,  
 278  
 uses of, 267, 278

double-angle cutter, 246  
 double-column planer, 325, 338

- double depth (DD), screw threads, 176  
 double-diameter mandrel, 131  
 double-tool cross slide, 223, 225, 226, 227  
 draw collet chuck, 125  
 drill drift, 72, 74  
 drilling, 30-31, 36  
     automatic-cycle, 64  
     on automatic machines, 63-64  
     center, 139-140, 141, 142, 164  
     deep hole, 230  
     defined, 51, 80  
     on lathes, 153-154  
     precision, 63  
     rotary, 382  
     on turret lathe, 217  
     using twist drills, 51-63  
     ultrasonic, 380-382  
 drilling machines, 39-49  
     automatic, 63-64  
     back-gear, 45, 46  
     Bickford radial, 60, 61, 68, 72  
     Bickford upright, 64, 65  
     defined, 39  
     dial-type limit-setting controls, 63-64, 65  
     gang machines, 45, 46, 48, 49  
     holding devices, 71-80  
     horizontal-spindle, 45  
     multi-spindle, 45, 48  
     radial drill press, 45-48, 49  
     sensitive drill press, 41, 45  
     single-spindle, 45  
     types of, 45-48, 49  
     variable-speed upright drill press, 45, 46  
     vertical-spindle, 45  
 drilling operations, 30-31, 36, 51-63  
     automatic machines, drilling on, 63-64  
     boring, 30, 71, 81  
     counterboring, 49, 66, 69  
     countersinking, 49, 66, 69  
     defined, 80  
 drills, decimal and metric equivalents of, 53-55, 422-423  
 feed and speed, 59-63  
 grinding and buffing, 71  
 mortising, 71, 81  
 reaming, 49, 70-71  
 safety, 79-80  
 spot-facing operation, 66, 69-70  
 suggestions for, 59  
 tapping, 49, 64-66, 67, 68  
 trepanning, 71, 72, 81  
 twist drill, 52-58  
 drill press  
     back-gear, 45, 46  
     back gears on, 40, 42  
     base, 44, 49  
     basic construction of, 39-45  
     bench-type sensitive, 39, 40, 44, 49  
     boring on, 30, 71, 81  
     capacity, 44-45  
     chucks, 49, 71-72, 73, 81  
     defined, 39, 49  
     drilling, 51-63  
     feed, 44, 49  
     floor-type sensitive, 39, 41, 49  
     head, 39, 42, 45, 49  
     holding devices, 71-80  
     manual-feed, 45  
     operations performed on, 49, 51-80  
     parts of, 49  
     radial, 45-48, 49  
     rating, 44-45  
     sensitive, 41, 45  
     spindle, 39-40, 43, 49  
     successful operation of, 49  
     table, 43, 46, 49  
     turning, 31-32, 36  
     variable speed upright, 42, 45, 46  
     V-belt, 39, 49  
 drills  
     center punch, 51  
     decimal and metric equivalents of, 53-55

drills (*continued*)  
 drift, 72, 74  
 feed of, 49  
 fractional, cutting speeds, 62  
 number and letter sizes with decimal equivalents, 422–423  
 sleeve, 72, 74  
 socket, 72, 74  
 drills, twist, 52–58  
 center drill, 57  
 cutting edges, 57–58  
 elements of, 52  
 feed and speed, 59–63  
 grounding of, 57–58  
 high-helix, 56  
 low-helix, 56  
 oil-hole, 57  
 parts of, 53  
 procedures for using, 59, 80–81  
 sizes, 53–54  
 starting drill, 57  
 straight-flute, 55  
 straight-shank, 55, 56  
 types and applications, 55–57  
 uses of, 52–53  
 drill sleeve, 72, 74  
 drill socket, 72, 74  
 driver plate, 113, 114  
 driving mechanism, set up, 275–278  
 drop hammer, 35, 36  
 double-ram vertical boring mill, 83  
 double-station vertical boring mill, 83  
 duplex milling machine, 239, 240

**E**

eccentric, 156–157, 158  
 eccentricity, 156  
 electrical discharge machining (EDM) process, 35, 36, 369–376, 377  
 applications of, examples, 374–375  
 basic principle of, 370

defined, 370–371  
 machine operations, 371–373  
 operations performed, 373–376  
 uses of, 369  
 electrochemical machining (ECM) process, 35, 365–369  
 advantage of, 376–377  
 basic principle of, 366  
 defined, 366–367  
 machine operations, 367–368  
 operations performed, 368–369  
 uses of, 365–366, 376  
 electrochemical milling, 36  
 electrode, 370  
 electroerosion, 370, 377  
 electroforming, 365–377  
 electrical discharge machining (EDM) process, 369–376  
 electrochemical machining (ECM) process, 365–369  
 uses of, 373, 376  
 electrolytic machining, 35  
 electron beam machining, 35, 36  
 electronic computers, applications, 36–37, 397–402, 403  
 electrospark forming, 35, 36  
 electrospark machining, 370, 377  
 enclosed standard-lead driving mechanism, 275  
 end mill, 246  
 English to metric conversion table, 417–418  
 even-gearied lathe, 177  
 explosive forming, 35  
 external thread, 175, 185–187  
 extra-fine thread screw thread series (UNEF), 172, 174

**F**

faceplates, lathes, 125–126, 149–150, 164  
 facing operation, lathes, 140–142  
 feed(s)  
 drill, 49  
 drill press, 44, 49

lathe operations, 137–138  
 milling machines, 257–261,  
 265  
 power band saws, 12, 23  
 shapers, 321  
 slotters, 350–351  
 feed stops  
 automatic, 198–200, 207  
 ball-type cross-feed, 199–200,  
 207  
 carriage, 198–199  
 cross-slide, 199–200  
 micrometer carriage, 198, 207  
 female center, 128  
 ferrous metals, cutting, 22  
 filing, on the lathe, 162–163  
 fine-thread screw thread series  
 (UNF), 172, 173  
 fine-tooth cutters, 247  
 finishing cuts, lathes, 140,  
 146–148  
 fission fragment exposure and  
 etching, 35  
 flexible blades, 2  
 floor-type horizontal boring  
 machines, 94  
 floor-type sensitive drill press, 39,  
 41, 49  
 fly cutter, 246  
 follower rest, 195, 196, 207  
 forging machine, 35, 36  
 formed cutter, 246  
 four-jaw (independent) chucks,  
 122–123  
 four-position length and depth  
 stop, 198–199  
 four-position stop roll attachment,  
 214–215  
 form-relief grinder, 354  
 fractional drills, cutting speeds,  
 62  
 friction cutting speeds, common  
 metals, 17–18  
 friction sawing, 17–18, 23  
 friction-type tapping attachment,  
 66  
 full diameter, 175

**G**  
 gang drilling machines, 45, 46, 48,  
 49  
 gap-bed lathe, 110  
 gas forming, 35  
 gear cutting, indexing for, 298  
 gear-cutting attachment, 204, 207  
 geared-head lathe, 112  
 grinders  
 bench, 353, 354  
 diagram of, 353  
 form-relief, 354  
 pedestal, 353  
 surface, hand-operated, 355  
 ultrasonic, 383  
 grinding, 36, 71  
 abrasives and, 382  
 centerless, 359  
 defined, 33–36  
 honing, 35  
 lapping, 35  
 nonprecision, 353, 363  
 precision, 353, 363  
 surface, 357, 360  
 types of, 353, 359  
 ultrasonic, 382  
 grinding attachment, 204, 205  
 grinding wheels, 355–358, 363  
 dressers, 356  
 faces, 356  
 sizes and shapes, 355  
 standard marking system, 358  
 variations in, 356–357  
 grippers, robot, 391, 394

**H**  
 hacksaws, power, 1–4, 22  
 and band saws compared, 6  
 basic construction, 1–3  
 blades, 2–3, 22  
 capacity, 2  
 cutting speed, 4  
 operation of, 3–4  
 safety features, 2  
 half center, 129  
 half side cutter, 246  
 hand-operated surface grinder, 355

- hand reaming, 70  
 head  
     drill press, 39, 42, 45, 49  
     shaper, adjustment of, 320  
     vertical boring mill, 85  
     vertically adjustable, horizontal  
         boring machines, 95-97  
 headstock  
     lathes, general, 110-113  
     turret lathes, 211, 231  
 heavy hex bolts, nominal  
     dimensions of, 407-408  
 heavy hex cap screws, nominal  
     dimensions of, 407-408  
 heavy hex jam nuts, nominal  
     dimensions of, 410-411  
 heavy hex nuts, nominal  
     dimensions of, 410-411  
 heavy hex structural bolts,  
     nominal dimensions of, 408  
 heavy square nuts, nominal  
     dimensions of, 411-412  
 helical cutter, 246  
 helical dividing head, 272-275,  
     278  
 helix angle, 175  
 hex bolts, nominal dimensions of,  
     406-407  
 hex cap screws, nominal  
     dimensions of, 406-407  
 hex jam nuts, nominal dimensions  
     of, 409  
 hex nuts, nominal dimensions of,  
     409  
 hex thick nuts, nominal  
     dimensions of, 409  
 high-helix twist drill, 56  
 hobbing machines, 33  
 holding devices, 74-80, 195-198  
     angle plate, 77-78  
     chucks, 71-72, 73, 119-125  
     for circular workpiece, 311-313  
     clamps, 78-79, 306-308, 332,  
         339  
     for cutters, 71-74  
     for drilling machines, 71-80  
     faceplates, 125-126  
 follower rest, 195, 196, 207  
 lathe centers, 126-129  
 lathe dogs, 113, 129-130,  
     142-143  
 mandrels, 130-131  
 milling machines, 242-246  
 parallels, 75, 77  
     for planers, 332, 339  
     for shaper operations,  
         305-318  
 sleeves and sockets, 72, 74  
 steady rest, 195-198, 207  
 step blocks, 79  
 straps, 78-79  
 T-bolts, 78, 306  
 tool or cutter holders, 71-74  
 V-blocks, 76-77  
 during vertical boring mill  
     operations, 87-89  
 vise, 2, 3, 5, 74-75, 76, 314  
     for work and setup, 74-80  
 hole-type stop pins, 309  
 honing, 34, 49  
 hook-tooth saw blades, 6-7, 16  
 horizontal boring machines,  
     94-104, 105-106  
     basic construction of, 95-99  
     boring on, 103-104  
     classification of, 94-95  
     drilling with a jig, 101-102  
     drilling without a jig, 99-101  
     facing, 104-105  
     operations, 99-105  
     rating, 95  
     uses of, 94, 95  
     vertically adjustable head,  
         95-97  
     vertically adjustable table,  
         97-99  
 horizontal-spindle drilling  
     machines, 45  
 horizontal turret lathe,  
     210, 231  
 hot machining, 35  
 hydraulic power slide, 202  
 hydraulic press, 34, 36  
 hydroforming, 35

- I**
- inclined slot-type stop pins, 309
  - index center, 267
  - index circles, determining which to use, 292–294
  - index crank, 268, 274, 281, 285, 299
  - index head, 267, 281. *See also* dividing heads
  - indexing
    - angular, 297
    - block, 298, 299
    - calculation of, 286–289
    - compound, 289–294, 299
    - compound angular, 297–298, 299
    - compound differential, 294–295
    - defined, 281
    - determining which circles to use, 292–294
    - differential, 294–296, 299
    - direct, 282–284, 298–299
    - methods of, 282–298
    - multiple, 298, 299
    - plain, 284–289, 299
    - rapid, 282–284, 298–299
    - simple differential, 294–295
    - zero hole, 268, 283–284
  - indexing plate, 281, 298
  - index pin, 268, 285
  - index plate(s)
    - defined, 119, 281–282
    - and dividing heads, 264, 268, 274, 298–299
    - diagram of, 283
    - holes in, 284
  - index plate stop, 285–286
  - index wheel, 281, 298
  - industrial robot, 389
  - inserted-tooth cutter, 246
  - inside diameter, 175
  - interlocking side cutter, 246
  - internal thread, 175, 186–187
  - International Metric thread system, 170
- J**
- jacks, 243

- K**
- key-drive spindle, 120, 121
  - knee-and-column milling machines, 233–236, 240
  - knurling, 155–156
- L**
- lag screws, nominal dimensions of, 412
  - lapping, defined, 34
  - lard oil, as coolant, 261
  - laser (light beam) cutting, 35
  - lathe attachments, 195–208
    - automatic devices, 207
    - automatic feed stops, 198–200
    - bed turret, 204, 206, 208
    - carriage stops, 198–199
    - cross-slide stop, 199–200
    - follower rest, 195, 196
    - gear-cutting attachment, 204, 207
    - grinding attachment, 204, 205
    - micrometer carriage stop, 198, 207
    - milling attachment, 203–204, 207
    - steady rest, 195–198, 207
    - swivel taper bar, 201
    - tailstock turret, 205–207, 208
    - taper attachment, 200–202, 207
  - tool-post grinder, 204, 205, 207–208
  - tool-post turret, 207, 208
  - tracer attachment, 202–203, 207–208
  - turret attachments, 204–207, 208
  - work support devices, 195–198
- lathe bed, 107, 109, 110, 111
- lathe carriage, 109, 113, 115, 151–153
- lathe centers, 126–129
- alignment of, 138–139
- lathe dogs, 113, 129–130, 142–143

- lathe operations, 31, 135–165  
 alignment of lathe centers, 138–139  
 boring, 155  
 center drilling, 139–140, 164  
 center holes, importance of, 139, 164  
 cutoff tool, 149  
 cutting speeds, 135–137, 164  
 cutting tool, height of, 143–145, 164  
 depth of cut, 138  
 drilling, 153–154  
 facing, 140–142  
 feed, 137–138  
 filing, 162–163  
 finishing cuts, 140, 146–149  
 finishing tool, application of, 147–148  
 knurling, 155–156  
 left-hand tools, 148  
 leveling and, 135  
 mounting on centers, 142–143  
 planning, importance of, 163–164  
 precision of, 163  
 premachining, 135–140, 164  
 proficiency in, 135  
 reaming, 154–155  
 roughing cuts, 140, 145–146  
 taper turning, 157–163, 164  
 turning, 142–157, 164, 224, 225  
 turning an eccentric, 156–157  
 work mounted on the angle plate, 151  
 work mounted on the carriage, 151–153  
 work mounted on the faceplate, 149–150, 164  
 lathes, 31, 36, 107–132  
 apron, 115, 118, 119  
 attachments, 195–208  
 back-gear, 110  
 basic construction of, 110–119  
 bed, 110, 111  
 boring on, 155, 164, 220  
 carriage, 109, 113, 115, 151–153  
 centers, 126–129, 138–139, 318  
 chucks, 119–125  
 compound rest, 113, 116–117  
 cross slide, 113, 115  
 cutting tools on, 143–145  
 design and functions, 107  
 dogs, 113, 129–130, 142–143  
 driver plate, 113, 114  
 even-gear, 177  
 faceplates, 125–126, 149–150, 164  
 facing operation, 140–142  
 feed mechanism, 118–119  
 functional diagram of, 108  
 headstock, 110–113  
 holding devices, 119–131  
 index plate, 119  
 lead screw, 118, 119  
 length of the bed, 107  
 mandrels, 130–131  
 multiple-spindle, 132  
 multiple-tool, 132  
 odd-gear, 177  
 parts of, 132  
 quick-change gearbox, 119, 120, 182, 185  
 reaming on, 154–155  
 reversing lever, 119  
 saddle, 115, 116  
 size of, 107–109, 132  
 spindle, 112–113  
 swing, 107–108, 132  
 tailstock, 113, 114  
 thread-cutting on, 118–119, 167–192  
 tool post, 115, 116–117  
 tool-room, 110  
 turret, 31  
 types of, 109–110, 132  
 ways, 110, 111, 112  
*See also* turret lathes  
 lead, screw threads, 175  
 lead screw, lathe, 118, 119  
 length-measuring attachment, 199, 200

length of engagement, 175  
 length of the lathe bed, 107  
 left-hand turning tools, 148  
 limits, 175  
 live center, 126–127  
 loose pulleys, 330  
 low-helix twist drill, 56  
 lubrication  
     for milling machines, 242

**M**

machine reaming, 70–71  
 machine shop electronics  
     applications, 389  
     computerized measurements  
         with Ultra-Digit, 397–402  
 robots, 389–397

machine tools  
     automatic tool changer, 26  
     basic operations, 25–36  
     boring, 30  
     classification of, 30  
     complexity of, 25  
     design of, 25  
     developments in, 35, 36–37  
     drilling 30, 36  
     evolution of, 25, 36  
     grinding, 33–36  
     metal forming, 36  
     milling, 32, 36  
     numerically controlled, 25  
     operation of, illustrated, 26–29  
     planing, 33, 36  
     quill up/quill down position, 27  
     reaming, 31  
     tapping, 31  
     technology and, 25  
     turning, 31–32, 36  
     vertical spindle machining center,  
         26

magnetic forming, 35, 36  
 major diameter, 175  
 mandrels  
     double-diameter, 131  
     lathes, 130–131  
     straight-lathe, 131  
     tapered, 131

manipulator, robots, 390, 393  
 manual-feed drill press, 45  
 maximum allowance, 173  
 mechanical dresser, 356  
 mechanical press, 34, 36  
 metal forming, 34, 36  
     tools needed for, 34–35, 36  
 metals, friction cutting speeds for,  
     17–18  
 micrometer carriage stop, 198,  
     207  
 micrometer table attachment,  
     millings machines, 264, 265  
 milling, 32, 36  
 milling attachment, 203–204,  
     207  
 milling cutters, 247  
     sharpening, 247–249  
 milling machine operations,  
     241–265  
     attachments and accessories,  
         263–265  
     cleaning the machine, 242, 265  
     climb milling, 253–254  
     conventional milling, 253  
     coolants, 261, 265  
     cutter rotation, direction of,  
         253–254  
     feeds, 257–261, 265  
     locating the cutter, 254–255  
     machining operations, 242,  
         261–263  
     mounting the cutter and arbor,  
         250–253  
     mounting the workpiece,  
         242–246, 265  
     oiling the machine, 242, 266  
     preliminary operations, 242  
     safety, 241, 265  
     selecting the cutter, 246–247  
     sharpening milling cutters,  
         247–249  
     speeds, 255–257, 265  
     taking the milling cut,  
         261–263  
 milling machines, 233–240  
     adaptation, 233

milling machines (*continued*)  
 attachments and accessories, 263-265  
 basic construction and classification, 233-239  
 bed-type, 238-239  
 cleaning, 242, 265  
 coolants for, 261, 265  
 defined, 233, 239  
 dividing heads, 267-278  
 duplex, 239, 240  
 feed, 257-261, 265  
 hobbing machines, 32  
 knee-and-column, 233-236, 240  
 locating the cutter, 254-255  
 micrometer table attachment, 263, 264  
 mounting the cutter, 250-253  
 mounting the work on, 242-246, 265  
 oiling, 242, 265  
 operation of, 233, 239-240  
 plain, 235-237, 240  
 plain horizontal, 236-237  
 planer type, 32  
 selecting the cutter, 246-247  
 sharpening the cutter, 247-250  
 speed, 255-257, 265  
 spindle, 235  
 spline mills, 238, 240  
 thread mills, 238, 240  
 types of, 236-239  
 universal, 237, 238  
 universal dividing head, 262, 263  
 uses of, 233, 240  
 vertical, 237, 239  
 vertical milling attachments, 265  
 minimum allowance, 173  
 minor diameter, 175  
 mortising, 71, 81  
 motor reverse control (for tapping), 66, 67  
 multiple indexing, 298, 299  
 multiple-spindle lathe, 132  
 multiple toolholder, 228  
 multiple-tool lathe, 132

multi-spindle drilling machines, 45, 48

## N

negative compounding, 291-22  
 neutral space, 175  
 nicked cutter, 246  
 nominal swing, 107  
 nonferrous saws, 18-19, 20  
 nonprecision grinding, 353, 363  
 number and letter sizes of drills with decimal equivalents, 422-423  
 number of threads, 175

## O

odd-gearied lathe, 177  
 offhand grinding. See nonprecision grinding  
 offset slide, turret lathe, 212  
 oil-hole twist drill, 57  
 open-side planer, 325, 338  
 outside diameter, 175

## P

parallels, 75, 77, 314, 315  
 pedestal grinder, 353  
 pitch, 175  
 pitch diameter, 175  
 plain cutter, 246  
 plain dividing head, 268-269, 270, 274, 278  
 plain horizontal milling machine, 236  
 plain indexing, 284-289, 299  
 calculation of on the standard driving head, 286-289  
 and compound indexing combined, 294  
 defined, 284  
 dividing-head sector, use of, 284-286  
 gearing arrangement, 284, 299  
 plain milling machines, 235-237, 240  
 plain slide, turret lathe, 211  
 plain vise, 314, 315

**planers**

- basic construction of, 325–331
- bed, 325, 339
- broaches, 33
- clamping, 332, 339
- columns, 327, 339
- crossrail, 327–328, 339
- cutting tools used on, 331–332, 338–339
- defined, 33, 325, 338
- diagram of, 326
- double-column, 325, 338
- holding devices, 332, 339
- open and crossed-belt drive, 330
- open-side, 325, 338
- operations, 332–338
- parts of, 339
- and shapers compared, 325, 338
- size of, 325
- table, 328, 339
- table drive, 329–331, 339
- toolhead, 328, 339
- types of, 325, 338
- uses of, 325, 338
- planer-type milling machine, 33
- planing operations, 332–338
  - at an angle, 334–337
  - defined, 33, 36
  - curved surfaces, 337
  - helix (work on centers), 337–338, 339
  - horizontal surfaces, 332–333
- plasma forming, 35
- positive compounding, 290
- power band saws, 4–18, 22
  - average speeds and cutting rates, 14–16
  - basic construction of, 4–7
  - blades, 6–8, 22
  - capacity, 6
  - classification of, 4–5
  - common problems and their connections, 12–14
  - cutting fluids, recommended, 10–12
  - feeds, 12, 23

- friction cutting speeds for common metals, 17–18
- and hacksaws compared, 6
- operation of, 7–18
- power feed, 44, 49
- power hacksaws, 1–4, 22
  - and band saws compared, 6
  - basic construction, 1–3
  - blades, 2–3, 23
  - capacity, 2
  - cutting speed, 4
  - operation of, 3–4
  - safety features, 2
- power rapid traverse, dividing heads, 276, 278
- precision drilling, 63
- precision grinding, 353, 363
- profile (contour) sawing, 8–9
- punch press, 34, 36

**Q**

- quick-change gearbox, 119, 120, 182, 185
- quick-change gear lathes, 182–183
- quill up/quill down position, machine tools, 27

**R**

- r/afd* relationship, 382
- radial drill press, 45–48, 49
- raker-set saw blade, 7, 15
- ram(s)
  - offset, 212
  - plain, 211
  - shapers, 304, 323
  - slotters, 341
  - universal, 212
- ram-type turret lathes, 210, 211–212, 231
- rapid indexing, 282–284, 298–299
- rapid power traverse, slotters, 350, 352
- rapid-traverse cross-slide attachment, 215, 216
- reaming
  - defined, 31, 49
  - hand, 70

- reaming (*continued*)  
 on lathes, 154–155  
 machine, 70–71  
 reference materials, 405–423  
 American Standard cap screws, 416  
 American Standard hexagon socket, slotted headless, and square-head setscrews, 414–415  
 American Standard machine screws, 413–414  
 colors and approximate temperatures for carbon steel, 406  
 decimal equivalents, squares, cubes, square and cube roots, and circumferences and areas of circles, (from 1/64 to 5/8 inch), 418–419  
 decimal equivalents, squares, cubes, square and cube roots, and circumferences and areas of circles, (from 41/64 to 1 inch), 420  
 English to metric conversion table, 417–418  
 heavy hex bolts, nominal dimensions of, 407–408  
 heavy hex cap screws, nominal dimensions of, 407–408  
 heavy hex jam nuts, nominal dimensions of, 410–411  
 heavy hex nuts, nominal dimensions of, 410–411  
 heavy hex structural bolts, nominal dimensions of, 408  
 heavy square nuts, nominal dimensions of, 411–412  
 hex bolts, nominal dimensions of, 406–407  
 hex cap screws, nominal dimensions of, 406–407  
 hex jam nuts, nominal dimensions of, 409  
 hex nuts, nominal dimensions of, 409  
 hex thick nuts, nominal dimensions of, 409  
 lag screws, nominal dimensions of, 412  
 number and letter sizes of drills with decimal equivalents, 422–423  
 screw threads and tap drill sizes, 420–421  
 square-head bolts, nominal dimensions of, 409–410  
 square nuts, nominal dimensions of, 411–412  
 reversing lever, 119  
 robots  
 applications, 36–37, 389  
 arm, 390–391  
 base, 390  
 basic construction of, 390–395  
 classification of, 389  
 complete system, illustrated, 392  
 grippers, 391, 394  
 industrial, 389  
 machining system, illustrated, 390  
 manipulator, 390, 393  
 motion, 394  
 parts of, 389  
 power, 403  
 teach pendant, 391  
 uses of, 395–397, 403  
 workshop duties, 395–397  
 wrist, 394  
 root, screw threads, 177  
 roughing cuts, lathes, 145–146
- S**
- saddle  
 lathes, 115, 116  
 milling machines, 235  
 shapers, 302, 323  
 saddle-type turret lathes, 210–212, 231  
 safety  
 abrasive metal finishing, 362–363  
 drilling, 79–80

milling machine operations, 241, 265  
 power hacksaws, 2  
 sanders, belt, 359, 361, 363  
 saws  
     circular, 18-22, 23  
     power band, 4-18, 22  
     power hacksaws, 1-4, 22  
 screw thread(s)  
     Acme, 167, 169, 183, 192  
     allowance, 172-173  
     American National, 168, 192  
     American Standard Buttress, 167, 170  
     American Standard for Unified miniature, 170  
     American Standard Stub Acme, 169  
     angle of thread, 173  
     axis of screw, 174  
     base of thread, 174  
     basic, 174  
     change-gear calculations, 177-183  
     coarse-thread series (UNC), 171-172  
     common forms of, 192  
     crest, 175  
     crest clearance, 175  
     cutting, 188-191, 192  
     cutting oil, 188  
     cutting tool, 183-187, 192  
     Dardelet, 170  
     defined, 177  
     depth of engagement, 175  
     depth of thread, 175  
     double depth (DD), 176  
     external thread, 175  
     extra-fine thread series (UNEF), 172, 174  
     fine-thread series (UNF), 172, 173  
     finishing the end of, 191  
     fitting and checking, 190-191  
     forms, 167-170, 192  
     helix angle, 175  
     internal thread, 175

International Metric system, 170  
 lead, 175  
 left-hand, 167  
 length of engagement, 175  
 limits, 175  
 major diameter, 175  
 minor diameter, 175  
 neutral space, 175  
 number of threads, 175  
 pitch, 17, 188  
 pitch diameter, 175, 192  
 right-hand, 167  
 root, 177  
 series, 171-172, 192  
 setup for cutting, 195-188  
 side of thread, 177  
 square, 167, 169, 183-184, 192  
 systems, 167-172  
 and tap drill sizes, table of, 420-421  
 terminology, 172-177  
 thread-cutting operations, 185-191  
 thread-cutting tools, 183-185  
 thread dial indicator, use of, 190  
 thread stop, use of, 189  
 tolerance, 177  
 translation, 167  
 Unified, 167, 168-169, 192  
 Whitworth standard, 167, 170, 185, 192  
 screw thread forms  
     Acme, 167, 169, 183, 192  
     American National, 168, 192  
     butress, 167, 170  
     Dardelet thread, 170  
     International Metric system, 170  
     sharp-V, 167, 168, 183  
     square, 167, 169, 183-184, 192  
     Stub Acme, 169  
     translation, 167  
     Unified, 167, 168-169, 170, 192  
     Whitworth standard, 167, 170, 185, 192

- screw thread series  
 coarse-thread, (UNC), 171-172,  
 192  
 extra-fine thread (UNEF), 172,  
 174, 192  
 fine-thread (UNF), 172, 173,  
 192  
 scribe, 350, 352  
 sector, indexing, dividing head,  
 268, 284-285  
 sensitive drill press, 41, 45  
 shapers, 33, 301-323  
 adjusting the work, 318-319  
 base, 302, 323  
 basic construction of, 301-304  
 basic diagram of, 303  
 basic parts of, 323  
 braces for tall castings, 310-311  
 bull gear, 304  
 clamping the work, 306-308  
 crank type, 301, 323  
 crossrail, 302, 323  
 cutting speed, selecting proper,  
 321-323  
 cutting tools, selection of, 305,  
 323  
 defined, 301, 323  
 feed, selecting proper, 321  
 geared type, 301, 323  
 head adjustment, 320  
 holding circular workpieces,  
 311-313  
 holding devices, 305-318  
 irregularly shaped work bolted  
 indirectly to the table,  
 313-314  
 operations, 304-323  
 parts of, 323  
 and planers compared, 325, 338  
 ram, 304, 323  
 saddle, 302, 323  
 size of, 301, 323  
 special fixtures, 317  
 standard, 301, 323  
 stop pins, 309  
 stroke adjustment, 319-320  
 table, 302, 304, 323  
 table strip, 309-310, 311  
 taking the cuts, 320-321  
 toe dogs, 309, 310  
 types of, 301, 323  
 universal, 301, 302, 323  
 uses of, 301  
 vise and, 301, 314-317  
 work bolted directly to the table,  
 306  
 work held by a vise, 314-316  
 workpiece mounted between  
 centers, 317-318  
 sharp-V screw threads, 167, 168,  
 183  
 shear, 34, 36  
 short and long lead attachment,  
 275  
 side cutter, 246  
 side of thread, 177  
 simple differential indexing,  
 294-295  
 simple gears, 177-179  
 simple indexing. *See plain*  
*indexing*  
 single-angle cutter, 246  
 single-ram vertical boring mill, 83  
 single-spindle drilling machines,  
 45  
 single-station vertical boring mill,  
 83  
 skip-tooth saw blades, 6  
 slide, vertical boring mill, 84  
 slitting cutter, 247  
 slotters  
 adjusting stroke position and  
 length of stroke, 343-349  
 alignment of work, 344  
 basic construction of, 341-342  
 circular work, 346-349  
 clamping the work, 343  
 cutting tools, 349-350, 352  
 defined, 33, 341, 351  
 diagram of, 342  
 feeds and speeds, 350-351  
 operations, 342-349  
 power-feed mechanism, 341  
 ram, 341

- rapid power traverse, 350, 352  
 speeds and feeds, 352  
 straight or flat work, 344–345  
 table, 341  
 uses of, 341, 351–352
- slotting, 33  
 slotting cutter, 246  
 slotting machine. *See* slotters  
 soldering, ultrasonic, 385–387  
 spark forming, 35  
 speed  
     circular saws, 21  
     milling machines, 255–257, 265  
     milling on a lathe, 203  
     power band saws, 14–18  
     slotters, 350–351  
     spindle, 40, 110–112, 113,  
     222–223  
     *See also* cutting speeds  
 spindle  
     angular indexing, 297  
     camlock, 120, 121  
     compound angular indexing,  
     297  
     compound indexing, 289  
     differential indexing, 294–295,  
     299  
     dividing heads, 268, 278  
     drill press, 39–40, 43, 49  
     indexing, general, 283  
     key-drive, 120, 121  
     lathes, 112–113  
     milling machines, 235  
     plain indexing, 284  
     speed, 40, 110–112, 113,  
     222–223  
     spindle nose, 112–113, 120  
     spiral cutter. *See* helical cutter  
     spline mills, 238, 240  
     spot-facing operation, 66, 69–70,  
     101  
     square-head bolts, nominal  
     dimensions of, 409–410  
     square nuts, nominal dimensions  
     of, 411–412  
     square screw thread form, 167,  
     169, 183–184, 192  
     starting drill, 57  
     steady rest, 195–198, 207  
     steel, cutting, 4, 261  
     step blocks, 79, 243  
     step chuck, 221, 224  
     stop pins, 309  
     and table strip, 309–310, 311  
     and toe dogs, 309, 310  
     straight dog, 129  
     straight-flute twist drill, 55  
     straight-lathe mandrel, 131  
     straight-shank twist drill, 55, 56  
     straps, 78–79  
     stroke adjustment screw, 319, 343  
     superprecision turret lathes, 215,  
     217  
     surface grinder, hand-operated,  
     355  
     surface grinding, 357, 360  
     swarf, 379  
     swing, 107–108, 132  
     swivel taper bar, 201
- T**
- table  
     drill press, 43, 46, 49  
     planers, 328, 339  
     shapers, 302, 304, 323  
     slotters, 341  
     vertical boring mill, 85  
     vertically adjusted, horizontal  
     boring machines, 97–99  
 table drive, planers, 329–331, 339  
 table strip, 309–310, 311  
 table-type horizontal boring  
     machines, 94  
 tailstock, 113, 114  
     alignment of, 139, 140  
     setover, calculating, 159–161  
 tailstock turret, 205–207, 208  
 tap drill sizes, screw threads and,  
     table of, 420–421  
 taper  
     defined, 157, 164  
     measurement of, 157, 165  
 taper attachment, 200–202, 207,  
     215, 216

- tapered drill sleeve, 72, 74  
 tapered mandrel, 131  
 taper per foot, 157, 158–159, 160  
 taper turning, 91–92, 157–163,  
     164  
     with the compound rest,  
         161–162  
     lathe attachment for, 200–202  
     tailstock setover method of, 128,  
         201  
 tapping, 31, 49, 64–66, 68  
     automatic, 64, 66  
     defined, 64  
     friction-type attachment for, 66  
     motor-reverse control, 66, 67  
 T-bolts, 78, 306  
 thread-cutting operations  
     change-gear calculations,  
         177–183  
     cutting the threads, procedures  
         for, 188–191  
     fitting and checking threads,  
         190–191  
     lathes, 167–192, 231  
     preliminary setup for, 185–188  
     resetting the threading tool, 190  
     screw thread systems, 167–172  
     terminology, 172–177  
     thread dial indicator, use of, 190  
     thread stop, use of, 189  
     tools for, 183–185  
     thread dial indicator, 190  
     threaded spindle nose, 120  
     threading tool, resetting, 190  
     thread mills, 238, 240  
     thread stop, 189  
     three-jaw (universal) chucks,  
         121–122, 221  
     throw, 156  
     tight pulleys, 330  
     toe dogs, 309, 310  
     tolerance, 177  
     toolhead, planers, 328  
     tool post, 115, 116–117  
     tool-post grinder, 204, 205,  
         207–208  
     tool-post turret, 207, 208  
     tool-room lathe, 110  
     tracer attachment, 202–203,  
         207–208  
     translation screw thread forms,  
         167  
     trepanning, 71, 72, 81  
     troubleshooting  
         power band saws, 12–14  
     T-slots  
         planer table, 329  
         tool for cutting, 305, 323  
     turning  
         with a drill press, 31–32, 36  
         with lathes, 142–157, 164, 224,  
             225  
         with vertical boring mills, 89–94  
     turret(s)  
         defined, 31, 209  
         on turret lathes, 212–213  
     turret attachments, 204–207, 208  
     bed turret, 204, 206, 208  
     four-position stop roll  
         attachment, 214–215  
     rapid-traverse cross-slide  
         attachment, 215, 216  
     tailstock turret, 205–207, 208  
     taper attachment, 215, 216  
     tool-post turret, 207, 208  
     turret lathes, 31, 132, 209–232  
         attachments, 214–215  
         attachments, illustrations of,  
             215, 216–231  
         automatic devices, 232  
         basic construction of, 211–215  
         boring operation on, 220  
         chuck-unchuck lever, 214, 232  
         classification of, 210–211, 231  
         collet chuck, 214, 220, 232  
         cross-slide carriage, 213–214  
         cutoff operations on, 218–219  
         cutoff toolholder, 229  
         deep hole drilling on, 230  
         defined, 209  
         double-tool cross slide, 223,  
             225, 226, 227  
         drilling operation on, 217  
         evolution of, 209, 231

headstock, 211, 231  
 horizontal, 210, 231  
 internal turning operation on, 218  
 milling machines, 242-246  
 multiple toolholder, 228  
 objective of, 209  
 parallels, 75, 77  
 parts of, 211-213, 231-232  
 production threading on, 231  
 ram-type, 210, 211-212, 231  
 rapid-traverse cross-slide attachment, 215  
 saddle-type, 210-212, 231  
 spindle speed, controlling, 222-223  
 step chuck, 221, 224  
 superprecision, 215, 217  
 three-jaw chuck, 221  
 turning operations on, 224, 225  
 vertical, 210, 231

**twist drills**, 52-58  
 center drill, 57  
 cutting edges, 57-58  
 elements of, 52  
 feed and speed, 59-63  
 grounding of, 57-58  
 high-helix, 56  
 low-helix, 56  
 oil-hole, 57  
 parts of, 53  
 procedures for using, 59  
 sizes, 53-54  
 starting drill, 57  
 straight-flute, 55  
 straight-shank, 55, 56  
 types and applications, 55-57  
 uses of, 52-53

**U**

Ultra-digit computer system, 397-402  
 ROM chip, 399  
 sample output from, 400, 401  
 statistical analysis (Stat-An) software program, 397, 401

system components, 397-398, 399, 402  
 system printouts, 398-400  
 ultrasonic cutter, 382  
 ultrasonic cutting and forming, 35  
 ultrasonics in metalworking  
 abrasives, 379-380  
 advantages of, 385  
 cutting performance, 382-385  
 drilling, 380-382, 387  
 grinding and cutting, 382, 387  
 machining, 379  
 newer developments, 385  
 soldering and welding, 385-387  
 uses of, 379, 387  
 welding and soldering, 387  
 Unified screw threads, 167, 168-169, 192  
 universal dividing head, 262, 263, 269-272, 278  
 universal milling machines, 236, 237, 238, 240  
 diagram of, 234  
 universal shaper, 301, 302, 323  
 universal slide, turret lathe, 212  
 universal tilting table, drill press, 46, 48, 49  
 universal vise, 244, 314, 316  
 up-cutting, 253

## V

variable-speed upright drill press, 45, 46  
 V-belt, drill press, 39, 49  
 V-blocks, 76-77, 316  
 V-ways, 110, 112  
 vertical boring mills, 83-94, 105  
 basic construction of, 84-85  
 boring, 85-87  
 classification of, 83-84  
 conical turning by combination of vertical and horizontal feeds, 92-94  
 conical turning, 91-92  
 flat and cylindrical turning, 89-91  
 head, 85

vertical boring mills (*continued*)  
 holding the work, 87-89  
 operations, 85-94  
 size, 84, 105  
 slides, 84  
 swing, 84  
 table, 85  
 turning, 89-94  
 uses of, 83  
 vertical cutoff slide, 219  
 vertical knee-and-column mills,  
 237  
 vertical milling attachments, 265  
 vertical milling machine, 236, 237,  
 239  
 vertical-spindle drilling machines,  
 45  
 vertical spindle machining center,  
 26  
 vertical turret lathe, 210, 231  
 vibratory tanks, 363  
 vise, 5, 74-75  
 air-hydraulic, 75  
 circular saws, 19  
 combination, 76  
 drill press, 43  
 and hacksaws, 3-4  
 milling machine, 244-246  
 mounted on worktable, 2  
 plain, 314, 315  
 and power band saws, 4, 5  
 and shapers, 301, 314-317  
 universal, 244, 314, 316  
 work held by, 314-316

**W**

wavy-set saw blade, 7  
 ways, lathe, 110, 111, 112

welding, ultrasonic, 385-387  
 Whitworth screw threads, 167,  
 192  
 Whitworth Standard screw thread  
 form, 170  
 work holders, 74-80, 195-198  
 angle plate, 77-78  
 chucks, 71-72, 73, 119-125  
 for circular workpiece, 311-313  
 clamps, 78-79, 306-308, 332,  
 339  
 faceplates, 125-126  
 follower rest, 195, 196, 207  
 lathe centers, 126-129  
 lathe dogs, 113, 129-130,  
 142-143  
 mandrels, 130-131  
 milling machines, 242-246  
 parallels, 75, 77  
 for shaper operations, 305-318  
 sleeves and sockets, 72, 74  
 steady rest, 195-198, 207  
 step blocks, 79  
 straps, 78-79  
 T-bolts, 78, 306  
 V-blocks, 76, 77  
 Tool or cutter holders, 71-74  
 during vertical boring mill  
 operation, 87-89  
 vises, 2-3, 5, 74-75, 76, 314  
 worktable, 2, 5, 242  
 worm, 268  
 worm wheel, 268, 274  
 wrist, robot, 394

**Z**

zero front clearance, 143, 164  
 zero hole, 268, 283-284

