



Shielded Metal Arc Welding


Edgar Gleeson

Shielded Metal Arc Welding

Edgar Gleeson

Shielded Metal Arc Welding
Edgar Gleeson
ISBN: 978-1-64172-196-7 (Paperback)

© 2019 Larsen & Keller

 Larsen & Keller

Published by Larsen and Keller Education,
5 Penn Plaza,
19th Floor,
New York, NY 10001, USA

Cataloging-in-Publication Data

Shielded metal arc welding / Edgar Gleeson.

p. cm.

Includes bibliographical references and index.

ISBN 978-1-64172-196-7

1. Welding. 2. Welding--Equipment and supplies. 3. Welding--Safety measures.

I. Gleeson, Edgar.

TS227 .W45 2019

671.52--dc23

This book contains information obtained from authentic and highly regarded sources. All chapters are published with permission under the Creative Commons Attribution Share Alike License or equivalent. A wide variety of references are listed. Permissions and sources are indicated; for detailed attributions, please refer to the permissions page. Reasonable efforts have been made to publish reliable data and information, but the authors, editors and publisher cannot assume any responsibility for the validity of all materials or the consequences of their use.

Trademark Notice: All trademarks used herein are the property of their respective owners. The use of any trademark in this text does not vest in the author or publisher any trademark ownership rights in such trademarks, nor does the use of such trademarks imply any affiliation with or endorsement of this book by such owners.

The publisher's policy is to use permanent paper from mills that operate a sustainable forestry policy. Furthermore, the publisher ensures that the text paper and cover boards used have met acceptable environmental accreditation standards.

Printed and bound in China.

For more information regarding Larsen and Keller Education and its products, please visit the publisher's website www.larsen-keller.com

Table of Contents

Preface	VII
Chapter 1 Introduction to Shielded Metal Arc Welding	1
• Arc Weld	1
• How to do Arc Weld Properly	5
• Shielded Metal Arc Welding	8
• How to do Shielded Metal Arc Welding	15
• How to Avoid Troubleshooting in Shielded Metal Arc Welding	19
• Gas Shielded Metal Arc Welding	22
Chapter 2 Equipments used in Shielded Metal Arc Welding	28
• Power Sources	28
• Controls	32
• Electrode Holder	33
• How to make an Electrode Holder	33
• Shielded Metal Arc Welding Electrode	36
• How to Select the Right Stick Electrode	39
• How to Check the Quality of SMAW Electrodes before Fabrication	41
• Welding Cables	44
• How to Choose the Right Welding Cables	45
• Ground Clamps	47
• How to Improve Ground Clamps	48
Chapter 3 Types of Weld Joints	52
• Butt Weld	52
• How to Perform a Butt Weld using Electric Arc Welding	54
• Fillet Weld	57
• How to Perform a Fillet Weld	60
• Lap Joint	63
• Corner Joint	64
• Edge Joint	64
• How to Square, Clamp and Tack your Joints and Weld	65
Chapter 4 Shielded Metal Arc Weld: Problems and Solutions	74
• Weld Distortion	74
• How to Control Distortion in Welding	76
• How to Avoid Warping of Thin Plates	81
• How to Avoid Corrosion in Welding	82
• How to Prevent Undercutting in your Weld	83
• How to Avoid Poor Weld Appearance in Welding	85
• Cracking	86
• How to Prevent Weld Cracks	93
• How to Avoid Brittle Welds in Welding	94
• How to Avoid Spatter in Welding	95

Chapter 5	Welding Safety	97
	• Safety Practices in Welding	97
	• How to Improve Welding Safety	101
	• How to Select Protective Equipments to Stay Safe	102
	• How to Avoid Welding Arc Flash	111
	• How to Avoid Possible Shock Hazards	112
	• How to Avoid Fire Hazards	113
Chapter 6	Diverse Types of Arc Welding	116
	• Flux-cored Arc Welding	116
	• Gas Metal Arc Welding	128
	• How to use a MIG Welder	136
	• How to Mig Weld Aluminum	144
	• Gas Tungsten Arc Welding	146
	• How to TIG Weld	148
	• Plasma Arc Welding	156
	• Submerged Arc Welding	160
	• Carbon Arc Welding	172
	Permissions	
	Index	

Index

- A**
Acidic Electrode, 38
Alternator, 13, 30-31
Aluminum, 39-40, 48-51, 63, 83, 130-132, 134, 136, 142, 144-146, 148-150, 152
Angular Distortion, 74, 76
Arc Shielding, 2
Arc Welding, 1, 3, 8, 11, 14-15, 19, 22, 28-29, 31, 36, 41, 54, 58, 74, 97-98, 100, 102, 106, 112, 116, 118, 128, 131, 134, 137, 146-148, 156, 158, 160-162, 164-173, 176
Argon, 4, 61, 94, 120-121, 131-132, 135-136, 142, 145-146, 148-150, 158
- B**
Brazing, 1, 52, 63, 98, 106, 110, 147, 173
Butt Joints, 21, 52, 54, 130
Butt Welding, 52-54, 81
- C**
Carbon Arc Welding, 172-173, 176
Carbon Dioxide, 10, 61, 84, 116, 120-122, 128, 131-132, 134-136, 142, 145
Clamping, 33, 35, 52, 79, 82
Cold Cracking, 38, 86-88, 91
Corrosion, 37, 53, 64, 74, 82-83, 121-122, 147, 171
- D**
Deoxidizers, 2, 4, 13, 116, 122, 132, 169, 172
Distortion, 21, 61, 66, 73-81, 135, 158, 176
- E**
Electric Arc Welding, 54, 111
Electrode, 1-5, 7-14, 20-22, 28-29, 32-44, 54, 59, 71, 75, 80, 82, 84-87, 92-96, 112, 116-117, 119-123, 127-136, 141, 144-150, 152, 156-163, 165-176
Electrode Holder, 2, 5, 9, 11, 14, 28, 33, 39, 44, 112, 130, 152
- F**
Face Shield, 15, 104
Feed Roller, 23-26
Filler Metal, 1, 3, 9, 13, 40, 42-43, 64-65, 122, 133, 146
Fillet Welding, 53, 57, 59, 67
Flanges, 52, 58, 64, 172
Flux-cored Arc Welding, 3, 11, 14, 116, 118-122, 164
- G**
Gas Hose, 123, 129-130, 151
Gas Metal Arc Welding, 4, 11, 58, 118-119, 128, 130-131, 133, 137
Generator, 29-32, 119, 161
Ground Clamp, 5, 16, 28, 47
- H**
Helium, 4, 131-132, 146, 150, 158
Helmet, 10, 15, 17, 28, 54, 98, 101-102, 104-105, 134, 148
Hot Cracking, 86, 88, 90, 92-93
- I**
Intermittent Welding, 60, 77
Inverter, 12, 29, 31
- L**
Lap Joint, 52, 63, 70-71, 117, 127, 155
- M**
Metal Inert Gas Welding, 137
- N**
Nitrogen, 2, 22, 37, 99, 120, 131-132, 172
- O**
Oxygen, 2, 9, 22, 37, 61, 92-93, 99-100, 110, 120-121, 131-132, 134, 172
- P**
Plasma Arc Welding, 4, 156, 158
- R**
Rutile Electrode, 38
- S**
Safety Glasses, 6, 106, 111
Shielded Arc Electrode, 37
Shielded Metal Arc Welding, 1, 4-5, 8, 11, 14-15, 18, 22, 28-29, 36, 74, 97, 116, 122, 128, 133, 166
Shielding Gas, 2, 8, 22-24, 27, 61, 116, 120-124, 128-136, 140, 142, 144-146, 148, 157-158
Soldering, 1, 34, 63
Spatter, 4, 10, 26, 38, 42, 62, 74, 95, 105-106, 108-109, 121-122, 124-127, 129, 131-133, 135-136, 143, 158, 163, 169
Stick Welding, 3, 8, 39, 107
Submerged Arc Welding, 4, 160-162, 164-172

T

T-fillet Weld, 60, 62
Transformer, 12-13, 29-31, 44, 112, 119, 161
Transverse Shrinkage, 74-75
Tungsten Inert Gas, 146, 148

U

Ultraviolet Light, 10, 98, 103-104

W

Warping, 56, 60, 74, 81-82
Weld Pool, 3, 7-10, 13, 71-72, 74, 94, 121, 130, 132, 134-136, 142-143, 148, 156

Welding Cables, 11, 28, 44-45, 118, 123
Welding Circuit, 1, 28, 166, 173
Welding Gloves, 6, 54, 106, 112
Welding Machine, 5-6, 12, 15, 17, 32, 47, 54, 61, 118, 123, 141, 148, 160
Welding Power Source, 22, 28-29, 39, 129
Welding Sequence, 78-79, 82, 94
Welding Torch, 22-23, 25-27, 47, 62, 67, 120, 131, 158, 160
Welding Wire, 22-24, 26-27, 62, 116, 138
Wire Brush, 7, 17-18, 28, 57, 92, 134, 152