

We Support AWS



# WELDING

Skills, Processes and Practices  
for Entry-Level Welders



## BOOK 2

- Gas Metal Arc Welding
- Flux Cored Arc Welding

SC

671.52  
J45  
2010  
Bk. 2

LARRY JEFFUS • LAWRENCE BOWER

# Contents

Preface . . . . .	viii
AWS Acknowledgment . . . . .	xi
Acknowledgments . . . . .	xii
About the Authors . . . . .	xiii
<b>Chapter 1 Gas Metal Arc Welding Equipment, Setup, and Operation . . . . .</b>	<b>1</b>
<i>Introduction</i> . . . . .	2
<i>Metal Transfer</i> . . . . .	4
Axial Spray Metal Transfer . . . . .	5
Globular Transfer . . . . .	7
Pulsed-Spray Transfer: GMAW-P . . . . .	7
Shielding Gases for Spray or Pulsed-spray Transfer . . . . .	9
Buried-arc Transfer . . . . .	9
Short-circuiting Transfer: GMAW-S . . . . .	11
<i>Filler Metal Specifications</i> . . . . .	13
Filler Metal Selection . . . . .	14
Stainless Steel Electrodes . . . . .	15
<i>Aluminum and Aluminum Alloys</i> . . . . .	15
Aluminum Bare Welding Rods and Electrodes . . . . .	20
<i>Wire Melting and Deposition Rates</i> . . . . .	20
<i>Welding Power Supplies</i> . . . . .	21
Speed of the Wire Electrode . . . . .	23
Power Supplies for Short-circuiting Transfer . . . . .	23
Inductance . . . . .	25
<i>Molten Weld Pool Control</i> . . . . .	25
Shielding Gas . . . . .	26
Power Settings . . . . .	29
Gun Manipulation . . . . .	30
Travel Speed . . . . .	30
Electrode Extension . . . . .	30
Gun Angle . . . . .	31
<i>Equipment</i> . . . . .	33
Power Source . . . . .	34
Electrode (Wire) Feed Unit . . . . .	37
Push-type Feed System . . . . .	37

	Pull-type Feed System . . . . .	38
	Push-pull-type Feed System . . . . .	39
	Linear Electrode Feed System . . . . .	39
	Spool Gun . . . . .	40
	Electrode Conduit . . . . .	41
	Welding Gun . . . . .	41
	<i>Spot Welding</i> . . . . .	42
	<i>Face, Eye, and Ear Protection</i> . . . . .	44
	Face and Eye Protection. . . . .	44
	Ear Protection. . . . .	48
	<i>General Work Clothing</i> . . . . .	49
	<i>Special Protective Clothing</i> . . . . .	51
	Hand Protection . . . . .	51
	Body Protection . . . . .	52
	Waist and Lap Protection . . . . .	52
	Arm Protection . . . . .	52
	Leg and Foot Protection. . . . .	52
<b>Chapter 2</b>	<b>Gas Metal Arc Welding . . . . .</b>	<b>55</b>
	<i>Introduction</i> . . . . .	56
	<i>Setup</i> . . . . .	57
	<i>Gas Density and Flow Rates</i> . . . . .	65
	<i>Arc-voltage and Amperage Characteristics</i> . . . . .	68
	<i>Electrode Extension</i> . . . . .	70
	<i>Welding Gun Angle</i> . . . . .	73
	<i>Effect of Shielding Gas on Welding</i> . . . . .	74
	<i>Practices</i> . . . . .	77
	<i>Metal Preparation</i> . . . . .	78
	<i>Flat Position, 1G and 1F Positions</i> . . . . .	79
	<i>Vertical Up 3G and 3F Positions</i> . . . . .	84
	<i>Vertical Down 3G and 3F Positions</i> . . . . .	86
	<i>Horizontal 2G and 2F Positions</i> . . . . .	89
	<i>Overhead 4G and 4F Positions</i> . . . . .	91
	<i>Axial Spray Transfer</i> . . . . .	94
<b>Chapter 3</b>	<b>Flux Cored Arc Welding Equipment, Setup, and Operation . . . . .</b>	<b>113</b>
	<i>Introduction</i> . . . . .	114
	<i>Principles of Operation</i> . . . . .	114
	<i>Equipment</i> . . . . .	117
	Power Supply . . . . .	117
	Guns . . . . .	117
	Smoke Extraction Nozzles. . . . .	119
	Electrode Feed . . . . .	119

<i>Advantages</i> . . . . .	119
High Deposition Rate . . . . .	119
Minimum Electrode Waste . . . . .	119
Narrow Groove Angle . . . . .	120
Minimum Precleaning . . . . .	120
All-position Welding . . . . .	120
Flexibility . . . . .	120
High Quality . . . . .	120
Excellent Control . . . . .	121
<i>Limitations</i> . . . . .	121
<i>Electrodes</i> . . . . .	121
Methods of Manufacturing . . . . .	121
Electrode Cast and Helix . . . . .	124
<i>Flux</i> . . . . .	125
Flux Cored Steel Electrode Identification . . . . .	128
Metal Cored Steel Electrode Identification . . . . .	130
Care of Flux Core Electrodes . . . . .	130
<i>Shielding Gas</i> . . . . .	131
<i>Welding Techniques</i> . . . . .	132
Gun Angle . . . . .	132
Forehand/Perpendicular/Backhand Techniques . . . . .	134
Travel Speed . . . . .	136
Mode of Metal Transfer . . . . .	137
Electrode Extension . . . . .	138
Porosity . . . . .	138
<b>Chapter 4 Flux Cored Arc Welding . . . . .</b>	<b>143</b>
<i>Introduction</i> . . . . .	144
<i>Practices</i> . . . . .	145
<i>Flat-position Welds</i> . . . . .	151
<i>Square-groove Welds</i> . . . . .	152
<i>V-Groove and Bevel-Groove Welds</i> . . . . .	154
Root Pass . . . . .	155
Filler Pass . . . . .	156
Cover Pass . . . . .	157
<i>Fillet Welds</i> . . . . .	160
<i>Vertical Welds</i> . . . . .	164
<i>Horizontal Welds</i> . . . . .	170
<i>Overhead-position Welds</i> . . . . .	175
<i>Thin-gauge Welding</i> . . . . .	180
<b>Appendix . . . . .</b>	<b>197</b>
<b>Glossary . . . . .</b>	<b>199</b>
<b>Index . . . . .</b>	<b>203</b>

# Index

*Italic* page numbers indicate material in tables or figures.

- acidic flux, 127
- air-cooled guns, 117-118
- AISI numbering, 15, 16-17, 129-130
- alloying elements, 15, 75, 114, 126
- aluminum and aluminum alloys
  - bare welding rods and electrodes, 15, 20, 37
  - as deoxidizers, 78, 114, 125
  - as filler metal, 15
  - filler metals for joining, 13, 18-19
  - in flux, 128
  - overview, 15-21
  - shielding gas effect on, 26, 27, 75
- American Iron and Steel Institute (AISI)
  - numbering, 15, 16-17, 129-130
- American Welding Society. *See* AWS
- amperage (amps)
  - axial spray metal transfer and, 94
  - defined, 21
  - droplet detachment and, 25
  - flux core arc welding and, 138
  - low, 165, 168-169
  - pinch effect and, 137
  - range, 11, 13, 24, 165
  - short-circuiting transfer and, 11, 79
  - splatter and, 29
  - surges, 30
  - voltage and, 29-30, 68-70
  - wire-feed speed and, 23, 30, 68
- amplitude, 7
- antispatter, 92, 93
- aprons, welders, 52
- arc
  - buried, 9-10
  - forces, 132, 135
  - high inductance and, 24-25
  - spot welds, 42, 62
  - stabilizers, 9, 26, 74, 126
  - strike, 157
  - travel speed and, 30, 136
- arc voltage, 26, 30, 68-70, 126, 148
- arc welding helmets, 7, 45, 46, 47
- argon (Ar) gas. *See also* shielding gases
  - bead shape and, 29
  - density of, 29
  - history of use, 2, 4, 9
  - mixtures containing, 5, 9, 11-15, 74-75
  - overview of, 26, 27-28, 77
  - pure, 9, 12, 74
- arm protection, 52, 53
- austenitic stainless steel, 13, 29
- automatic (AU) welding process, 2, 3
- AWS A5.3, 15
- AWS A5.4, 15
- AWS A5.6, 13
- AWS A5.9, 13, 13, 15
- AWS A5.10, 13, 15
- AWS A5.14, 13
- AWS A5.16, 13
- AWS A5.18, 13
- AWS A5.19, 13
- AWS A5.20, 128
- AWS A5.22, 128
- AWS A5.29, 128
- AWS D1.1, 12
- AWS filler metal numbering system, 14
- AWS filler metal specs, 13
- AWS SENSE QC-10 2004, 101, 102, 104
- axial spray metal transfer
  - current settings for, 94
  - ionization and, 131, 132
  - overview of, 5-6, 137
  - practicing, 94-96
  - shielding gases for, 9
- backhand welding
  - gun angle and, 73, 74
  - monitoring weld pool in, 80, 81
  - overview, 31-33
  - technique, 135-136
- backing strip, 155
- bare metal welding rods, 15, 20
- basic flux, 127
- bevel-groove welds, 154
- beveling, 138, 152, 154
- bird-nesting, 58, 60, 64, 146, 148
- bright metal, 78, 79, 141
- buildup
  - heat, 30, 31, 71, 143
  - splatter, 92, 133, 134
  - weld, 25, 32, 73, 136, 165, 181
- buried-arc transfer process, 9-10
- burn-back, 137, 159
- burn-back time, 43, 44
- burn-off rate, 23, 136, 138
- burn-through
  - avoiding, 12, 25, 86, 133, 181
  - in spot welding, 42, 44
- butane lighters, 51
- carbon dioxide
  - advantages and disadvantages of, 9-10, 29
  - blends, 12, 26, 27-28, 74-75
  - history of use, 2, 9-10
  - pure, 11, 75, 132
- carbon steel
  - amperages for, 23, 68
  - filler metals, 13-14
  - short-circuiting transfer mode for, 11-12
  - spray transfer mode for, 5-6
- cast, 64, 64, 124, 124
- CC (constant current), 9, 21, 71
- chromium and chromium alloys, 9, 29, 75, 114, 128
- circuit resistance, 24-25, 70-71, 148
- cleaning
  - action, cathodic, 9
  - of base metal, 97, 120
  - to bright metal, 78, 79, 141
  - weld, 98
- coiling, 41
- coils, 123, 124
- cold feed switch, 64, 149
- "cold" weld, 85
- columbium, 128
- concave weld face, 156, 161, 162
- conduit liner, 41, 58-59, 60, 62, 64, 148
- constant current (CC), 9, 21, 71
- constant potential (CP), 9, 21, 23, 30-31, 70-71, 114
- constant voltage (CV), 9, 21, 23, 30-31, 70-71, 114
- contact tube, 41, 43, 59, 62, 148
- contact tube-to-work distance, 25, 31, 32

- contamination and impurities  
 atmospheric, 114, 131  
 within base metal, 115-116, 117, 125, 127  
 from moisture, 130  
 surface, 97, 115, 138-139  
 from turbulence, 66, 92  
 within weld pool, 128
- convex weld faces, 136, 155-156, 162, 165, 169
- copper and copper alloys, 13-14, 26, 27, 29
- corrosion, 9, 10, 20, 114, 121
- cover pass, 154, 157
- CP (constant potential), 9, 21, 23, 30-31, 70-71, 114
- cracking, 15, 20, 139, 161
- critical (transition) current, 5-7, 8, 137
- critical welds, 155-156
- current  
 critical (transition), 5-7, 8, 137  
 DCEN, 138  
 DCEP (DCRP), 5, 9, 138  
 defined, 21  
 deposition rate and, 5-7, 21  
 effects on weld of, 6, 25, 68-71, 92, 175  
 globular transfer and, 7, 137  
 setting the, 68-70, 79, 94  
 short-circuiting transfer and, 11-12, 24, 25, 30  
 spray transfer and, 7, 8, 137  
 stickout (electrode extension) and, 30-31, 70-71  
 typical welding machine, 35  
 volt-ampere characteristics and, 21-24  
 wire-feed speed and, 23, 114
- CV (constant voltage), 9, 21, 23, 30-31, 70-71, 114
- cylinder, gas, 58, 66, 131, 145, 146
- DAV (drooping arc voltage), 21
- DCEN (direct current electrode negative), 138
- DCEP (direct current electrode positive), 5, 9, 138
- DCRP (direct current reverse polarity), 5, 9, 138
- deoxidizers  
 mill scale and, 78  
 overview, 115-116, 120, 125  
 porosity and, 26, 75  
 slag and, 131  
 table of, 78, 125
- deposition efficiency, 21
- deposition rates, 4, 20-21
- direct current electrode negative (DCEN), 138
- direct current electrode positive (DCEP), 5, 9, 138
- direct current reverse polarity (DCRP), 5, 9, 138
- drafts, dealing with, 66, 67, 139, 140
- drooping arc voltage (DAV), 21
- ductility, 20, 126, 127
- E70T-1 electrodes, 151, 153, 164, 181
- E70T-5 electrodes, 151, 164, 181
- E70T-10 electrodes, 128-129
- E71T-1 electrodes, 151, 153, 164, 181, 188
- E71T-11 electrodes, 151, 153, 164, 181, 192
- earmuffs, 48, 49
- earplugs, 49
- electric potential, defined, 21
- electrode conduit liner, 41, 58-59, 60, 62, 64, 148
- electrode extension (stickout), 30-31, 70-72, 138, 139
- electrode wire. *See also* feeder systems; filler metals; flux  
 bird-nesting, 58, 60, 64, 146, 148  
 care of, 65, 130-131, 139, 150  
 cast, 64, 64, 124, 124  
 classification of, 14-20, 127-130, 132  
 coated, 13  
 deposition rate of, 4, 20-21  
 diameters, 11, 13, 72, 114, 121-123  
 diameters, appropriate use, 21, 119, 120-123, 137-138  
 extension (stickout), 30-31, 70-72, 138, 139  
 filler, 14-21  
 history of, 2-3, 114  
 manufacturing technology, 12, 121-124  
 solid, 14-15  
 strength of, 37  
 threading, 62-65, 149-150  
 waste in FCAW, SMAW, 119
- ER70S-X filler wires, 14-15
- ER1100, 20
- ER4043, 20
- ER5356, 20
- ER5556, 20
- experiments  
 effect of electrode extension, 71-72  
 effect of gun angle, 73-74  
 effect of shielding gas changes, 75-77  
 setting gas flow rate, 66-68  
 setting the current, 68-70
- eye protection, 7, 44-48
- face protection, 7, 44-48
- face shield, 46, 47, 48
- "fast-freeze," 128
- FCAW. *See* flux cored arc welding (FCAW)
- feeder systems. *See also* feed rollers; wire-feed speed  
 coil supports, 124  
 cold feed switch and, 64, 149  
 dual, 117, 119  
 installing, 58, 59, 63, 146-148  
 retract button, 150  
 short-circuiting transfer and, 11  
 synergic systems, 7  
 types of, 37-41
- feed rollers. *See also* feeder systems; wire-feed speed  
 bird-nesting and, 58, 60, 64, 146, 148  
 compression, 64-65  
 dual, 117, 119  
 overview, 34, 38, 40-41  
 sizing, 58-59, 60, 147  
 tension, 63  
 threading, 62, 64-65, 149
- ferrite, 128
- ferrous alloys, 9, 26, 74-75, 121
- filler metals, 123. *See also* electrode wire  
 minimum waste of, 119-120  
 overview of, 2-3, 13-20  
 selector guide for joining aluminum, 18-19  
 selector guide for joining stainless steel, 16-17  
 solid wire, 14-15  
 specifications for, 13
- filler passes, 154, 156-157
- fillet welds, 160-164, 169
- fire safety, 51
- flash glasses, 44
- flowmeter regulator, 58, 59, 67, 146, 147
- flow rate, 66-68, 92
- flux  
 classifications table, 127  
 cored electrodes, 128-131  
 dual feeders and, 119  
 manufacture of, 121, 122, 131  
 moisture in, 138-139  
 overview, 114-115  
 roller pressure and, 150  
 types of, 125-128
- flux cored arc welding (FCAW)  
 advantages of, 119, 120-121  
 care of electrodes, 130-131  
 direct current electrode negative, 138  
 limitations of, 121  
 overview, 57, 114

- principles of operation, 114–117
- setup for, 57, 144–149
- workmanship qualification tests, 190, 193
- fluxing agents, 125–126
- forehand welding
  - advantages, disadvantages of, 134–135
  - monitoring the weld pool in, 80
  - overview, 31–33, 34, 74
  - technique, 80, 133, 134–135
  - weld shape and, 73, 133
- free bend testing, 141
- frequency, 7
- fusion
  - defects in, 12, 30, 85, 152, 165
  - depth of, 135
  - root, 161, 162, 184
- gases. *See* shielding gases
- gas flow rate, 66–68, 92
- gas nozzle, 43, 45, 92, 119, 139
- gas tungsten arc (GTA) welding, 4, 14–15, 20, 51
- globular transfer process, 7, 10, 27, 31, 137–138
- gloves, safety, 51, 51
- GMAW (gas metal arc welding)
  - equipment for, 33–41
  - filler metal for, 14–15
  - manufacturer's instructions, 62, 63
  - overview, 2–3, 4
  - setup for, 57–62, 77
  - shielding gases for, 9, 27–28
  - spot welding and, 42–43
  - workmanship qualification tests, 99, 106
- GMAW-P (pulsed-spray metal transfer), 7–9
- GMAW-S (short-circuiting transfer)
  - current settings for, 79
  - gun manipulation and, 30–31
  - inductance controls and, 25
  - overhead position and, 91
  - overview of, 10–13
  - power supplies for, 23–25
  - shielding gases for, 26, 27–28, 29, 75
- goggles, 44, 46
- grinding requirements, 141
- GTA welding, 4, 14–15, 20, 51
- guided bend testing, 141
- gun lead, 58, 148
- guns
  - air-cooled, 117–118
  - angle, 31–35, 66, 73–74, 132–136
  - assembly and setup, 41–43, 59, 61
  - backhand welding, 31–33, 73–74, 80–81, 135–136
  - examples, 42, 43, 57, 61, 118
  - forehand welding, 31–34, 73–74, 80, 133–135
  - manipulation, 30, 89, 92, 114, 175
  - operation, 64–68
  - spool, 40–41
  - switch, 41, 64, 68
  - water-cooled, 117–118
- hand protection, 42, 51
- helium
  - advantages of, 10, 12
  - density of, 66, 67
  - mixtures containing, 9, 26, 27, 74
  - overview, 29
  - pure, 74
  - specification tables for, 27–28, 77
- helix, 124
- horizontal welds, 89–91, 95, 132, 138, 170–174
- hot-rolled steel, 78, 79, 139
- hydrogen, 129–131, 133, 139, 140
- icicles, 91–92
- impurities. *See* contamination and impurities
- inductance control, 12, 24–25
- International Alloy Designation System, 15, 18–19
- interpass temperature, 97
- iron and ferrous alloys, 9, 26, 74–75, 121, 128. *See also* mill scale
- joints
  - beveled, 152
  - butt, 81, 153–154, 156–159
  - lap, 82, 160–162
  - tee, 82, 160–164
- knurling, 37
- lamellar tearing, 161
- leggings, safety, 52
- lime-based flux, 125, 127
- linear electrode feed system, 39–40
- liner. *See* electrode conduit
- low-alloy steel, 9, 12, 27–28, 77, 121
- low-carbon steel, 12, 151, 164, 181, 188, 192
- machine (ME) welding process, 2
- machine slope, 23–25
- magnesium and magnesium alloys, 13, 15, 20, 26, 27, 29
- magnetic particle testing, 141
- MAG welding, 2
- manganese, 15, 20, 75, 78, 127, 132
- metal active gas welding (MAG), 2
- metal inert gas welding (MIG), 2
- metal preparation, 78
- metal transfer methods, overview, 4–13
- ME welding process, 2
- MIG welding, 2
- mild steel, 6, 14, 37, 94, 127–129
- mill scale, 78, 79, 97, 116, 139, 141
- molten weld pool, 25–33
- molybdenum, 128
- multipass welds, 120, 127, 154, 156, 175
- neck protection, 50
- nick-break testing, 141
- nickel and nickel alloys, 13, 26, 27, 121
- nitrogen, 26, 27, 29, 114
- nozzle, 43, 45, 92, 119, 139
- nozzle-to-work distance, 4, 31, 32, 139
- OF welding, 20
- oil, 97, 141
- open circuit voltage, 24
- out-of-position welding, 28, 127–128, 134, 138, 144
- overhead-position welds, 91–94, 175–180
- overlap, 82, 156–157, 160, 172, 175
- oxidation. *See also* deoxidizers
  - base metal, 9, 14–15, 78, 125, 139
  - electrode wire, 131, 132
  - weld pool, 74, 114, 116, 126
- oxidizing (reactive) gases, 14–15, 26, 27, 74–75, 77, 126. *See also* shielding gases
- oxyfuel gas welding (OFW), 20
- oxygen, 26, 27–28, 74–75, 125, 132, 139
- paint, 42–43, 121, 141
- passes, types of weld, 154–157
- PA welding, 14
- perpendicular technique, 134, 135
- personal protective equipment (PPE). *See* protection
- pinch effect, 5, 24, 137
- plasma arc welding (PAW), 14
- porosity
  - deoxidizers to prevent, 125
  - mill scale and, 78, 79, 139, 141
  - moisture and, 130–131, 140
  - overview, 138–141
  - oxygen and, 125
  - shielding gases and, 26, 75, 77
  - testing for, 141
  - wind and, 139

- position
  - flat, 79-83
  - horizontal, 89-91
  - out-of-position, 28, 127-128, 134, 138, 144
  - overhead, 91-94, 175-180
  - spatter and, 135, 176
  - vertical, 84-89, 164-170
- postweld cracking, 139
- potassium, 114
- potential, electric, 21
- power supplies, 12-13, 21-25, 34-35, 36, 71, 114
- PPE. *See* protection
- practice
  - axial spray transfer, 94-109
  - flat position, 79-83
  - GMAW equipment setup, 58-62
  - horizontal position, 89-91
  - overhead position, 91-94
  - short-circuit metal transfer, 96-103
  - threading GMAW wire, 62-65
  - vertical down position, 86-89
  - vertical up position, 84-86
- practice plates, 145
- productivity, 56-57, 77, 121, 141, 144
- protection
  - body, 49-53, 176
  - ear, 48-49, 49
  - face and eye, 7, 44-48
  - pull-type feed system, 38-39
  - pulsed-spray metal transfer (GMAW-P), 7-9
  - push-pull-type feed system, 39, 39
  - push-type feed system, 37, 38
- reactive (oxidizing) gases, 14-15, 26, 27, 74-75, 77, 126. *See also* shielding gases
- refractory flux, 128
- reinforcement, 157
- resistance
  - arc, 11, 126
  - circuit, 24-25, 70-71, 148
  - creep, 114
- retract button, 65
- robotic welding, 2, 35, 135
- rollers. *See* feeder systems
- root edge, 159
- root face, 152, 157, 158
- root pass, 154, 155-156
- rust, 13, 14-15, 78, 97, 131, 141
- rutile-based flux, 125, 127
- safety. *See* protection
- safety boots, 50
- safety glasses, 45-47
- SAW, 2, 57
- SA welding process, 2, 57
- semiautomatic (SA) welding process, 2, 57
- shade lens, 45, 48
- sheet metal, 6-7, 12, 15, 120, 134
- shielded metal arc welding (SMAW), 2, 3, 21, 119, 155
- shielding gases. *See also* individual gases
  - density of, 65-66
  - dual shield, 131-132
  - effects on weld of, 74-77
  - flow rate of, 66-68, 92
  - history of, 2
  - inert, 9
  - mixtures, 5, 9, 74-77
  - selection of, 26-29, 131-132
  - self-shielding, 131-132
  - for spray/pulsed-spray transfer, 9
  - table of, 27-28
- short-circuiting transfer. *See* GMAW-S (short-circuiting transfer)
- silicon, 15, 20, 75, 78, 114, 128, 132
- slag
  - agents, 114
  - defined, 117
  - desirable effects of, 125
  - flux characteristics and, 127-128
  - inclusions, 125, 135, 144, 157, 160
  - shielding gas and, 4
  - undesirable effects of, 131, 133, 135, 155-156
- slope, 23-25
- smoke extraction nozzles, 114, 116, 119
- sodium, 114
- solenoids, 33, 58, 64, 93, 148
- solid state electronics, 7
- spatter
  - antisplatter, 92-93
  - arc and, 10, 10, 126, 131, 161
  - in axial spray metal transfer, 5-6
  - current and, 92, 175
  - electrodes and flux, 127, 135, 138
  - excessive, 9, 144
  - globular metal transfer and, 9-10, 137
  - gun angle and, 133, 134, 176
  - inductance and, 12, 25
  - shielding gas and, 9-10, 26, 29, 69, 74-75
  - in short-circuiting transfer, 12, 24
  - slope and, 24-25
  - stickout and, 176
  - turbulence and, 92
  - weave pattern and, 84, 165
  - welding position and, 135, 176
- spool drag, 65, 150
- spool gun, 40-41
- spools, 123-124
- spot welding, 42-43, 44, 45
- spray transfer mode. *See also* axial spray metal transfer
  - conditions required for, 5
  - current and, 7, 8, 137
  - GMAW-P (pulsed-spray metal transfer), 7-9
  - shielding gases for, 9
  - spatter and, 5-6
  - weld pool and, 5, 5
  - workmanship qualification test, 106
- square-groove welds, 152-154
- stainless steel
  - electrodes, 15, 37, 129-130
  - filler metals for, 13, 16-17
  - GMAW-S and, 12
  - shielding gas for, 9-10, 27-28, 29, 77
- steel. *See also* carbon steel; stainless steel
  - hot-rolled, 78, 79, 139
  - low-alloy, 9, 12, 27-28, 77, 121
  - low-carbon, 12, 151, 164, 181, 188, 192
  - mild, 6, 14, 37, 94, 127-129
- stickout (electrode extension), 30-31, 70-72, 138, 139
- stringer beads, 80, 156-157
- submerged arc welding (SAW), 57
- supply cylinder, 58, 66, 131, 145, 146
- synergic systems, 7-9
- tack welds, 83, 155, 160, 161
- tensile strength, 14, 20
- tensioner, wire-feed, 65, 149
- terminals, 58, 148
- testing, 12, 68-70, 141
- thin-gauge welding, 12, 120, 127, 138, 180-189
- threading wire, 62-65, 149-150
- titanium and titanium alloys, 13, 29, 75, 78, 114, 125
- transformer rectifier power supply, 21, 22
- transition (critical) current, 5-7, 8, 137
- transverse face bend, 102
- transverse root bend, 102
- travel angle, 31-35, 66, 73-74, 132-136
- travel speed, 30, 92, 135, 136, 165, 175
- tube-to-work distance, 25, 31, 32
- tungsten gas, 4, 14, 51
- ultrasound testing, 141
- ultraviolet light, 45, 47, 48, 50, 144



- underbead cracking, 161
- undercutting
  - defined, 91, 136
  - fluxing agents and, 125-126
  - shielding gases and, 26, 74
  - visual inspection of, 157, 189
- vanadium, 29, 75, 114
- venturi effect, 66
- vertical positions, 84-89, 164-170
- V-groove welds, 154
- visibility of weld, 79, 121, 133-135, 148
- visual inspection, 78, 157
- voltage
  - amperage and, 29-30, 68
  - arc, 26, 30, 68-70, 126, 148
  - current and, 12, 21-24
  - defined, 21, 114
  - inductance and, 24-25
  - open circuit, 24
  - range, 165
  - shielding gases and, 26-29
  - slope and, 23-25
  - stickout and, 30
- volt-ampere characteristics, 21-24
- water-cooled guns, 117-118
- water pressure regulator, 118
- weave beads, 156-157
- weave patterns, 30, 84-86
- weld bead contour, 9, 28, 33-34, 91, 156, 172
- welding
  - history and overview of, 2-3, 7
  - methods of, 3
    - spot, 42-43, 44, 45
- welding cables, 34, 145, 148, 158
- welding clothes, 49-53, 176
- welding guns. *See* guns
- welding helmets, 7, 45, 46, 47
- welding procedure specification (WPS), 68
- weld pool, 25-33
- welds
  - bevel-groove, 154
  - "cold," 85
  - concave face, 156, 161, 162
  - convex face, 136, 155-156, 162, 165, 169
  - critical, 155-156
  - fillet, 160-164, 169
  - multipass, 120, 127, 154, 156, 175
  - spot, 42-43, 44, 45
  - square-groove, 152-154
  - tack, 83, 155, 160, 161
  - V-groove, 154
- wind, dealing with, 66, 67, 139, 140
- wire deposition rates, 4, 20-21
- wire electrode. *See* electrode wire
- wire electrode cast, 64, 64, 124, 124
- wire feeder. *See* feeder systems
- wire-feed speed
  - amperage and, 68
  - for carbon steel, 23, 68
  - defined, 23
  - if unspecified, 151, 164, 181, 188, 192
  - measuring, 23, 68
  - synergic systems and, 9
- wire-feed tensioner, 65, 149
- wire-feed unit. *See* feeder systems
- wire melting rate, 20
- wire welding, 2
- work angle, 31-35, 66, 73-74, 132-136
- work clothing, 49-53, 176
- workmanship qualification test
  - FCAW-G, 190, 193
  - GMAW, 99, 106
- WPS, 68
- X ray testing, 141
- zirconium, 78, 114, 125