



# Welding

## Skills and Techniques

 Larsen & Keller

Jaden Patterson



# Welding: Skills and Techniques

Jaden Patterson

 Larsen & Keller  
www.larsen-keller.com



Welding: Skills and Techniques  
Jaden Patterson  
ISBN: 978-1-64172-330-5 (Paperback)

© 2020 Larsen & Keller

 Larsen & Keller

Published by Larsen and Keller Education,  
5 Penn Plaza,  
19th Floor,  
New York, NY 10001, USA

### Cataloging-in-Publication Data

Welding : skills and techniques / Jaden Patterson.  
p. cm.

Includes bibliographical references and index.

ISBN 978-1-64172-330-5

1. Welding. 2. Welding--Guidebooks. 3. Metal-work. I. Patterson, Jaden.

TS227 .W45 2020  
671.52--dc23

This book contains information obtained from authentic and highly regarded sources. All chapters are published with permission under the Creative Commons Attribution Share Alike License or equivalent. A wide variety of references are listed. Permissions and sources are indicated; for detailed attributions, please refer to the permissions page. Reasonable efforts have been made to publish reliable data and information, but the authors, editors and publisher cannot assume any responsibility for the validity of all materials or the consequences of their use.

Trademark Notice: All trademarks used herein are the property of their respective owners. The use of any trademark in this text does not vest in the author or publisher any trademark ownership rights in such trademarks, nor does the use of such trademarks imply any affiliation with or endorsement of this book by such owners.

The publisher's policy is to use permanent paper from mills that operate a sustainable forestry policy. Furthermore, the publisher ensures that the text paper and cover boards used have met acceptable environmental accreditation standards.

Printed and bound in China.

For more information regarding Larsen and Keller Education and its products, please visit the publisher's website  
[www.larsen-keller.com](http://www.larsen-keller.com)



# Table of Contents

<b>Preface</b>	<b>VII</b>
<b>Chapter 1 An Introduction to Welding</b>	<b>1</b>
• How to Weld	3
• Welder	6
• How to Become a Welder	8
• How to Become an Underwater Welder	9
• How to Pass a Welding Certification Test	14
• How to Learn Welding as a Hobby	21
• How to Improve your Stick Welding Technique	30
• How to Select your First Welding Machine	36
<b>Chapter 2 Welding Metals</b>	<b>46</b>
• Stainless Steel	46
• How to Weld Stainless Steel	48
• How to Weld Steel with a Flux Cored Welder	51
• Cast Iron	57
• How to Weld Cast Iron	59
• Wrought Iron	63
• How to Weld Wrought Iron	64
• Aluminium	65
• How to Weld Aluminium	65
• How to Clean and Prepare Aluminium Filler and Base Metals before Welding	70
• Nickel	72
• How to Weld Nickel Alloys	73
• Bronze	75
• How to Weld Bronze	75
• Copper	81
• How to Weld Copper	82
• Titanium	83
• How to Weld Titanium and its Alloys	86
<b>Chapter 3 Welding Equipment</b>	<b>91</b>
• Auto Darkening Welding Helmet	91
• Welding Clamps	100
• Welding Magnets	103
<b>Chapter 4 Oxy-fuel Gas Welding</b>	<b>107</b>
• How to Set Up an Oxy Acetylene Torch	109
• How to Operate an Oxy Gasoline Cutting Torch System	121



Chapter 5	<b>Arc Welding</b>	<b>127</b>
	• How to do Gas Metal Arc Welding	132
	• How to Improve MIG Welding	146
	• How to MIG Weld Thick Structural Plates	149
	• How to MIG Weld Square Tube	151
	• How to MIG Weld Square Tube with Flat Plate	154
	• How to Fix an Erratic Arc in MIG Welding	155
	• How to Weld Tig Welding	157
	• How to do Shielded Metal Arc Welding	165
	• Pipe Welding Build up using SMAW	175
	• How to do Flux Cored Arc Welding	176
Chapter 6	<b>Resistance Spot Welding</b>	<b>188</b>
	• How does a Spot Welding Work	192
	• How to Improve Spot-Welding Performance	193
	• How to Protect yourself from Welding Fumes in Resistance Welding	197
Chapter 7	<b>Welding Safety</b>	<b>200</b>
	• How to Prevent Electric Shock during Welding	200
	• How to Deal with Welding Fumes and Gases	202
	• How to Prevent Welding Fires	207
	• How to Choose the Best Welding PPE	209
	• Head and Eye Protection Tips for Welders	212
	• Safety Tips During Resistance Spot Welding	213
	• Safety Tips During Gas Welding	215
	• Safety Tips During Arc Welding	222

**Permissions**

**Index**



# Index

- A**  
Adjustable Wrench, 57, 110, 114  
Alternating Current, 2, 27, 79, 128-129, 132, 167-169, 174-175, 201-202  
Aluminum, 1, 5, 7, 36, 77, 79, 86, 133, 148, 159-160, 163  
Arc Welding, 1-3, 7, 14-15, 22, 30, 36, 61, 65, 105, 127-130, 132-133, 136, 157, 165-167, 169-171, 173, 175-176, 222, 224  
Argon, 2, 47, 49-50, 66, 76, 85-86, 89-90, 134, 148, 150, 159, 172-173
- B**  
Base Metals, 7, 70-71, 200  
Blast Furnace, 58  
Butt Welding, 2, 65, 198-199
- C**  
C-clamps, 53, 106  
Carbon Content, 57-59, 64, 197  
Carbon Steel, 52, 63, 65, 133, 148, 150, 193, 196  
Cast Iron, 1, 46, 57-63, 102, 128, 170  
Chromium, 46, 73, 130, 220  
Corrosion Resistance, 46, 84-86, 88, 130  
Cylinder Blocks, 58
- D**  
Dc Positive Polarity, 27  
Deficient Welding, 43  
Direct Current, 2, 27, 79, 128-129, 167-169  
Dive Training, 11  
Dust Particles, 38  
Duty Cycle, 38, 41, 128, 194
- E**  
Electric Arc Furnace, 47  
Electric Shocks, 41, 200  
Electrode Positive, 31, 168, 170, 174
- F**  
Flux Cored Welder, 51-52  
Friction Welding, 2  
Fuse Blows, 39  
Fusion Zone, 3
- G**  
Gas Metal Arc Welding, 15, 22, 36, 127-129, 132  
Gas Mixture, 49-50, 129  
Gas Welding, 1, 7, 107, 133, 215
- H**  
Helium, 49-50, 74, 76, 86, 89, 148  
Hot Electrode Holder, 41
- I**  
Iron-making Techniques, 1
- M**  
Malleable Iron, 63  
Material Capacity, 38  
Metal Alloys, 64, 82  
Metal Fabrication, 14-15, 24  
Metal Feed Rate, 18  
Metallurgy, 3, 9, 46, 63  
Molten Metal, 2, 20-21, 47, 67, 136, 166-167, 173, 189, 207-209, 211, 215, 225  
Molybdenum, 46, 84
- N**  
Non-ferrous Metal, 66
- O**  
Oxidation Process, 70  
Oxide Film, 70-71  
Oxide Layer, 70-72  
Oxy-fuel Welding, 7  
Oxyacetylene, 1, 7, 65, 76-77, 107-108
- P**  
Pig Iron, 58, 64  
Plasma Arc, 15, 71, 130  
Plugged Valve, 43  
Polarity Switch, 40  
Porosity, 16, 30, 33, 43, 60, 65, 70-71, 74, 148, 169, 175  
Power Supply, 39, 68, 127, 175  
Production Process, 47, 86
- R**  
Resistance Welding, 1-2, 7, 188, 192, 197-199
- S**  
Scrap Metal, 22, 51, 138, 180



Shielded Metal Arc Welding, 7, 14, 30, 61, 65, 127-129, 132, 165-167, 173

Shielding Gas, 26, 36, 48-50, 66, 69, 74, 76, 127-129, 133-134, 137, 142, 146, 148, 172-173

Silicon Content, 58

Spray Transfer, 67, 69, 148

Stainless Steel, 36, 46-51, 64, 69, 72-73, 86, 88, 102, 130, 133, 148, 193

Steel Alloy, 46

Steel Plate, 16, 108

Stick Welders, 30, 91

Stutter-step Pattern, 34

Submerged Arc Welding, 7, 65, 128-129

## T

Tensile Strength, 64, 85-86

Tensile Stress, 59-60, 62

## U

Underwater Welder, 1, 9-13

## W

Wear Resistance, 58

Weld Chart, 54

Welding Gun, 25-26, 28, 48-50, 53, 132-135, 142-143

Welding Jacket, 38

Welding Joint, 71

Wire Brush, 30, 52-53, 56, 66, 72, 81, 160, 176-177, 182, 185

Wrought Iron, 46, 59, 63-65